

Inventory Data

Structure Name:	Concession 4 NDR Lot 30 Culvert	Site Number:	B-105
District:		Road Name:	Concession 4
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	250
Structure Type:	CSP (arch)	Overall Struct. Width:	25 m
Number of Spans:	2	Roadway Width:	6.6 m
Direction of Structure:	North-South	Total Deck Length:	7.4 m
GPS Coordinates (Degrees)		Span (s):	5.4 m
General	Latitude: 44.211104	Total Deck Area:	185 sq.m
	Longitude: -80.895677	Current Load Limit:	0

Inspection Data

Date of Inspection:	10-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	12
Special Notes:	Culvert is in good condition, recommend railing system repair.

Overall Inspection Summary

BCI: 74

Next Inspection: 10-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1992	Contract Number When Built:	
Latest Biennial Inspection:	March 23, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	74	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: East Barrel: View from south.



Description: West Barrel: View from south.



Description: West Barrel: View from north.



Description: Railing systems: Medium to severe rot throughout with localized 100% section loss.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-105"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="2.7"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="25"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="424"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-105"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="5.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="North Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="B-105"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="6.6"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="7.4"/> m
Material:	<input type="text" value="Asphalt"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="49"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-105"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-105"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Barriers	Site Number:	B-105
Element Name:	Railing systems	Width:	0 m
Element type:	Flexi beam with steel posts	Height:	0.8 m
Sub-element:		Length:	24 m
Material:	Steel	Count:	2
Location:		Total Quantity:	48 m
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	Structural
Maint needs:	Barrier/railing system repair	Maint. Time Period:	2 Year

Condition Data (m):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:	None Recommended	Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:

Medium to severe rot throughout with localized 100% section loss.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-105"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="5.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="South Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Baseline, 0.3 km North of Grey Rd 4 Culvert



South Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Baseline, 0.3 km North of Grey Rd 4 Culve	Site Number:	G-132
District:		Road Name:	Baseline
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	50
Structure Type:	CSP (arch)	Overall Struct. Width:	13 m
Number of Spans:	2	Roadway Width:	6.6 m
Direction of Structure:	North-South	Total Deck Length:	4.5 m
GPS Coordinates (Degrees)		Span (s):	3.6 m
General	Latitude: 44.191241	Total Deck Area:	58 sq.m
	Longitude: -80.768758	Current Load Limit:	0

Inspection Data

Date of Inspection:	11-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	16
Special Notes:	Fill on structure = 0.2 m. Culvert is in poor condition. Barrel is misshaped. Inadequate fill over culverts. Recommend monitor deformations until replaced.

Overall Inspection Summary

BCI: 62

Next Inspection: 22-Mar-25

Additional Investigation Required:	Monitor Deformations and Cracking	Priority:	Medium
Additional Investigation Cost:			
Rehabilitation Needs:	Replace		
Rehabilitation Timing:	1 to 5 years		
Total Rehabilitation Budget Costings:	\$261,000.00	Engineering Fee:	\$31,320

Historical Data

Year Built:	1990	Contract Number When Built:	
Latest Biennial Inspection:	March 22, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	62	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: North barrel: View from east.



Description: South barrel: View from west.



Description: South barrel: View from east.



Description: Barrel: Bottom appears to be flattening.



Description: Barrel: Moderate deformation mid barrel.



Description: Inlet: Severe scouring of south barrel.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-132"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="1.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.2"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="21.4"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="161"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="Load carrying capacity"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Bottom appears to be flattening. Moderate deformation mid barrel. North barrel at time of inspection: Height - 1.07m, Width: 1.85m. South barrel at time of inspection: Height - 1.24m, Width: 1.83m. Both measured from West end.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-132"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="4.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.2"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text" value="East Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Severe scouring of south barrel.



Element Inspection

Element Group:	Decks	Site Number:	G-132
Element Name:	Wearing surface	Width:	6.6 m
Element type:		Height:	0 m
Sub-element:		Length:	4.5 m
Material:	Gravel	Count:	1
Location:		Total Quantity:	30 sqm
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:	None Recommended	Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-132"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-132"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="4.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.2"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text" value="West Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-132"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culvert (overall)"/>	Site Number:	<input type="text" value="G-132"/>
Element Name:	<input type="text" value="All Elements"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text" value="CSP Replacement"/>	Unit Cost:	<input type="text" value="\$4500 / sq.m"/>
Rehab time period:	<input type="text" value="1 - 5 Years"/>	Estimated Cost:	<input type="text" value="\$261,000"/>
Quantity:	<input type="text" value="58"/> sq.m		

General Comments:

Barrel has advanced deformations recommend monitor further deformations until replacement.

OSIM Biennial Inspection Report



Site Number:

B-118

Concession 14 NDR Lot 11 Culvert



East Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Concession 14 NDR Lot 11 Culvert	Site Number:	B-118
District:		Road Name:	Concession 14
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	50
Structure Type:	CSP (arch)	Overall Struct. Width:	16 m
Number of Spans:	1	Roadway Width:	6.6 m
Direction of Structure:	East-West	Total Deck Length:	2.4 m
GPS Coordinates (Degrees)		Span (s):	2.4 m
General	Latitude: 44.285975	Total Deck Area:	38 sq.m
	Longitude: -81.014148	Current Load Limit:	0

Inspection Data

Date of Inspection:	13-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	20
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 74	Next Inspection:	13-Jun-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1980	Contract Number When Built:	
Latest Biennial Inspection:	March 22, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	74	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: Improper splice bolt pattern, no cracking noted.



Description: Barrel: Light corrosion along waterline.



Description: Barrel: Moderate deformation mid barrel.



Description: West barrel: View from south.



Description: East barrel: View from north.



Description: West barrel: View from north.



Description: Wearing surface: Moderate erosion at edges.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-118"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="2.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.9"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="16"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="121"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>


Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Improper splice bolt pattern, no cracking noted. Light corrosion along waterline. Moderate deformation mid barrel.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-118"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="2.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.9"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-118"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="2.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.9"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text" value="South Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="B-118"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="6.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="2.4"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="16"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Moderate erosion at edges.



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-118"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-118"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

G-030

Concession 2 & 3E, Lot 3



North Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Concession 2 & 3E, Lot 3	Site Number:	G-030
District:		Road Name:	Concession 2
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	100
Structure Type:	Box Culvert Open Footing - Rigid	Overall Struct. Width:	9.75 m
Number of Spans:	1	Roadway Width:	8.5 m
Direction of Structure:	East-West	Total Deck Length:	7.3 m
GPS Coordinates (Degrees)		Span (s):	6.4 m
General	Latitude: 44.310179	Total Deck Area:	71 sq.m
	Longitude: -80.821420	Current Load Limit:	0

Inspection Data

Date of Inspection:	13-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	20
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 75

Next Inspection: 13-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1965	Contract Number When Built:	
Latest Biennial Inspection:	March 27, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	75	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from west.



Description: Hand Railings: Minor localized damage.



Description: Barrel: Medium vertical crack with wetness staining.



Element Inspection

Element Group:	Accessories (Attachments and Signs)	Site Number:	G-030
Element Name:	Signs	Width:	0 m
Element type:		Height:	0 m
Sub-element:		Length:	0 m
Material:	Steel	Count:	4
Location:		Total Quantity:	4 each
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Barriers"/>	Site Number:	<input type="text" value="G-030"/>
Element Name:	<input type="text" value="Hand Railings"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="7.3"/> m
Material:	<input type="text" value="Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="15"/> m
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (m):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Minor localized damage.



Element Inspection

Element Group:	<input type="text" value="Barriers"/>	Site Number:	<input type="text" value="G-030"/>
Element Name:	<input type="text" value="Railing Systems"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text" value="Flexi beam with timber posts"/>	Height:	<input type="text" value="1.05"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="33"/> m
Material:	<input type="text" value="Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="66"/> m
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (m):
Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-030"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="6.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.5"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="9.75"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="111"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Medium vertical crack with wetness staining.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-030"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="7.3"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.5"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="East Side"/>	Total Quantity:	<input type="text" value="59"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-030"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="7.3"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.5"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="West Side"/>	Total Quantity:	<input type="text" value="59"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="G-030"/>
Element Name:	<input type="text" value="Wearing Surface"/>	Width:	<input type="text" value="8.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="7.3"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="62"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-030"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-030"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	G-030
Element Name:	Foundation (below ground level)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	Cast-in-place Concrete	Count:	<input type="text"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text"/> each
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: 0 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/> 0		

General Comments:

No signs of settlement.

OSIM Biennial Inspection Report



Site Number:

B-114

Old Bridge Rd South Culvert



South Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Old Bridge Rd South Culvert	Site Number:	B-114
District:		Road Name:	Old Bridge Road
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	50
Structure Type:	Box Culvert Open Footing - Simple	Overall Struct. Width:	13.5 m
Number of Spans:	1	Roadway Width:	6 m
Direction of Structure:	North-South	Total Deck Length:	3.7 m
GPS Coordinates (Degrees)		Span (s):	3.1 m
General	Latitude: 44.159073	Total Deck Area:	50 sq.m
	Longitude: -80.949583	Current Load Limit:	0

Inspection Data

Date of Inspection:	10-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	12
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 73	Next Inspection:	10-Jun-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1950	Contract Number When Built:	
Latest Biennial Inspection:	March 27, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	73	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from west.



Description: Barrel: Light vertical cracks with wetness and leachate staining.



Description: Barrel: Shallow delamination throughout.



Description: Barrel: Shallow localized spall with exposed reinforcing.



Description: Wearing surface: Moderate potholes throughout.



Description: Wearing surface: Severe alligator cracking at shoulders.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-114"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="3.1"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.3"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="13.5"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="77"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Light vertical cracks with wetness and leachate staining. Shallow delamination throughout. Shallow localized spall with exposed reinforcing.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-114"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="3.7"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.3"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="East Side"/>	Total Quantity:	<input type="text" value="12"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-114"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="3.7"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.3"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="West Side"/>	Total Quantity:	<input type="text" value="12"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="B-114"/>
Element Name:	<input type="text" value="Wearing Surface"/>	Width:	<input type="text" value="6"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="3.7"/> m
Material:	<input type="text" value="Asphalt"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="22"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text" value="Structural"/>
Maint needs:	<input type="text" value="Asphalt Repairs"/>	Maint. Time Period:	<input type="text" value="2 Year"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Moderate potholes throughout. Severe alligator cracking at shoulders.



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-114"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-114"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	B-114
Element Name:	Foundation (below ground level)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	Cast-in-place Concrete	Count:	2
Location:	<input type="text"/>	Total Quantity:	2 each
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: 0 Good: 2 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/> 0		

General Comments:

No signs of settlement.

OSIM Biennial Inspection Report



Site Number:

G-035

Concession 2 & 3W, Lot 100, West Back Line Road



South Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Concession 2 & 3W, Lot 100, West Back L	Site Number:	G-035
District:		Road Name:	West Back Line
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	0
Structure Type:	Concrete Arch	Overall Struct. Width:	20.75 m
Number of Spans:	1	Roadway Width:	7.3 m
Direction of Structure:	East-West	Total Deck Length:	10.7 m
GPS Coordinates (Degrees)		Span (s):	10.21 m
General	Latitude: 44.304194	Total Deck Area:	222 sq.m
	Longitude: -80.664893	Current Load Limit:	0

Inspection Data

Date of Inspection:	12-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	22
Special Notes:	Culvert is in good to fair condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 73

Next Inspection: 12-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1940	Contract Number When Built:	
Latest Biennial Inspection:	March 24, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	73	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from west.



Description: Barrel: Medium to wide transverse cracks with leachate staining (1/2).



Description: Barrel: Medium to wide transverse cracks with leachate staining (2/2).



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-035"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="10.21"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="3.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="20.75"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="365"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Medium to wide transverse cracks with leachate staining.



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-035"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-035"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="10.21"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="3.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="East Side"/>	Total Quantity:	<input type="text" value="7"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-035"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="G-035"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="10.7"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="7.3"/> m
Material:	<input type="text" value="Asphalt"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="78"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Barriers"/>	Site Number:	<input type="text" value="G-035"/>
Element Name:	<input type="text" value="Railing systems"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text" value="Flexi beam with steel posts"/>	Height:	<input type="text" value="0.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="60"/> m
Material:	<input type="text" value="Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="120"/> m
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (m):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	G-035
Element Name:	Foundation (below ground level)	Width:	0 m
Element type:		Height:	0 m
Sub-element:		Length:	0 m
Material:	Cast-in-place Concrete	Count:	0
Location:		Total Quantity:	0 each
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:	None Recommended	Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:

No signs of settlement.

Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-035"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="10.21"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="3.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="West Side"/>	Total Quantity:	<input type="text" value="7"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):
Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:





G-148

Concession 6, West of Glenelg Rd 23 Culvert



East Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Concession 6, West of Glenela Rd 23 Culv	Site Number:	G-148
District:		Road Name:	Concession 6
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	100
Structure Type:	Box Culvert Open Footing - Rigid	Overall Struct. Width:	13 m
Number of Spans:	1	Roadway Width:	7 m
Direction of Structure:	East-West	Total Deck Length:	6.7 m
GPS Coordinates (Degrees)		Span (s):	5.7 m
General	Latitude: 44.248521	Total Deck Area:	87 sq.m
	Longitude: -80.724623	Current Load Limit:	0

Inspection Data

Date of Inspection:	12-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	25
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 75

Next Inspection: 12-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1980	Contract Number When Built:	
Latest Biennial Inspection:	March 24, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	75	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from north.



Description: Inlet: Light to medium cracking with leachate staining.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-148"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="5.7"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.33"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="13"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="109"/> sqm
Environment:	<input type="text" value="Benian"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-148"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="6.7"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.33"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="South Side"/>	Total Quantity:	<input type="text" value="14"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Light to medium cracking with leachate staining.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-148"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="6.7"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.33"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="North Side"/>	Total Quantity:	<input type="text" value="14"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-148"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-148"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Foundations"/>	Site Number:	<input type="text" value="G-148"/>
Element Name:	<input type="text" value="Foundation (below ground level)"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="0"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="0"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

No signs of settlement.

Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="G-148"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="7"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="6.7"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="47"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

G-197

Concession 8/9, Lot 10



West Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Concession 8/9, Lot 10	Site Number:	G-197
District:		Road Name:	Concession 8
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	100
Structure Type:	CSP (round)	Overall Struct. Width:	15 m
Number of Spans:	2	Roadway Width:	6.6 m
Direction of Structure:	East-West	Total Deck Length:	3.6 m
GPS Coordinates (Degrees)		Span (s):	3.6 m
General	Latitude: 44.265322	Total Deck Area:	54 sq.m
	Longitude: -80.740276	Current Load Limit:	0

Inspection Data

Date of Inspection:	12-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	25
Special Notes:	Culvert is in excellent condition showing no signs of structural distress.

Overall Inspection Summary

BCI: 98	Next Inspection:	12-Jun-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:		Contract Number When Built:	
Latest Biennial Inspection:	March 24, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	98	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: Moderate deformation at midspan in east barrel.



Description: West barrel: View from south.



Description: East barrel: View from north.



Description: West barrel: View from north.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-197"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="1.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.2"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="12.5"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="94"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Moderate deformation at midspan in east barrel. Recommend monitoring deformation at next inspection.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-197"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="1.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.2"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text" value="South Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="G-197"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="6"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="3.6"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="22"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-197"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-197"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Culverts	Site Number:	G-197
Element Name:	Outlet Components	Width:	1.8 m
Element type:		Height:	1.2 m
Sub-element:		Length:	0 m
Material:	Corrugated Steel	Count:	2
Location:	North Side	Total Quantity:	2 sqm
Environment:	Moderate	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:	None Recommended	Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

B-196

Welbeck Rd Culvert



East Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Welbeck Rd Culvert	Site Number:	B-196
District:		Road Name:	Welbeck Road
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	250
Structure Type:	Box Culvert Open Footing - Simple	Overall Struct. Width:	7.9 m
Number of Spans:	1	Roadway Width:	6.6 m
Direction of Structure:	East-West	Total Deck Length:	4.1 m
GPS Coordinates (Degrees)		Span (s):	3.1 m
General	Latitude: 44.275308	Total Deck Area:	32 sq.m
	Longitude: -80.893057	Current Load Limit:	0

Inspection Data

Date of Inspection:	13-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	20
Special Notes:	Culvert is in fair condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: **67**

Next Inspection: 13-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:		Contract Number When Built:	
Latest Biennial Inspection:	March 27, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	67	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from north.



Description: Barrel: Shallow to severe delaminations with exposed reinforcing throughout.



Description: Inlet: Shallow spill.



Description: Inlet: Light horizontal cracking with leachate staining.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-196"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="3.1"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="7.9"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="40"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Shallow to severe delaminations with exposed reinforcing throughout.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-196"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="4.1"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="South side"/>	Total Quantity:	<input type="text" value="6"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Shallow spall. Light horizontal cracking with leachate staining.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-196"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="4.1"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="North Side"/>	Total Quantity:	<input type="text" value="6"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Decks	Site Number:	B-196
Element Name:	Wearing Surface	Width:	6.6 m
Element type:		Height:	0 m
Sub-element:		Length:	4.1 m
Material:	Steel	Count:	1
Location:		Total Quantity:	27 sqm
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:		Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-196"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Recommend hazard signs.



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-196"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	B-196
Element Name:	Foundation (below ground level)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	Cast-in-place Concrete	Count:	<input type="text"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text"/> each
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: 0 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/> 0		

General Comments:

No signs of settlement.

Element Inspection

Element Group:	<input type="text" value="Retaining walls"/>	Site Number:	<input type="text" value="B-196"/>
Element Name:	<input type="text" value="Walls"/>	Width:	<input type="text" value="0.2"/> m
Element type:	<input type="text" value="I Type"/>	Height:	<input type="text" value="0.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="4.1"/> m
Material:	<input type="text" value="Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Light corrosion throughout.



OSIM Biennial Inspection Report



Site Number:

N-171

Concession 14, Lot 20



East Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Concession 14, Lot 20	Site Number:	N-171
District:	Concession 14	Road Name:	Concession Rd 14
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	200
Structure Type:	CSP (arch)	Overall Struct. Width:	12 m
Number of Spans:	1	Roadway Width:	6.2 m
Direction of Structure:	East-West	Total Deck Length:	3.5 m
GPS Coordinates (Degrees)		Span (s):	3.5 m
REVIEWED	Latitude: 44.088885	Total Deck Area:	42 sq.m
	Longitude: -80.910053	Current Load Limit:	0

Inspection Data

Date of Inspection:	30-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	23
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 74	Next Inspection:	30-Jul-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	2012	Contract Number When Built:	
Latest Biennial Inspection:	September 6, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	74.5	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: Minor deformations throughout.



Description: Barrel: View from east.



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="N-171"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="6.2"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="3.5"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text"/>
Location:	<input type="text" value="Over Barrel"/>	Total Quantity:	<input type="text" value="22"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-171"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="3.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-171"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="3.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-171"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="3.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="12"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="132"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

Minor deformations throughout.



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-171"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-171"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	N-171
Element Name:	Foundation (below ground)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	1
Location:	<input type="text"/>	Total Quantity:	1
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: 0 Good: 1 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

No signs of settlement.

Element Inspection

Element Group:	<input type="text" value="Barriers"/>	Site Number:	<input type="text" value="N-171"/>
Element Name:	<input type="text" value="Railing systems"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text" value="Flexi beam with steel posts"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="3.5"/> m
Material:	<input type="text" value="Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="7"/> m
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (m):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

G-126

Baptist Church Rd, Concession 8 Culvert



North Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Baptist Church Rd. Concession 8 Culvert	Site Number:	G-126
District:		Road Name:	Baptist Church Rd
County:	Grey County	Owner:	
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	100
Structure Type:	CSP (arch)	Overall Struct. Width:	16 m
Number of Spans:	2	Roadway Width:	6.6 m
Direction of Structure:	North-South	Total Deck Length:	3.6 m
GPS Coordinates (Degrees)		Span (s):	3.6 m
General	Latitude: 44.261224	Total Deck Area:	58 sq.m
	Longitude: -80.735543	Current Load Limit:	0

Inspection Data

Date of Inspection:	12-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	25
Special Notes:	Culvert is in excellent condition showing no signs of structural distress.

Overall Inspection Summary

BCI: 100

Next Inspection: 12-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1980	Contract Number When Built:	
Latest Biennial Inspection:	March 24, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	100	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: South barrel: View from west.



Description: North barrel: View from east.



Description: South barrel: View from east.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-126"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="1.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0.95"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="16"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="96"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-126"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="1.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0.95"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text" value="West Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-126"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="1.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0.95"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text" value="East Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-126"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-126"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Decks	Site Number:	G-126
Element Name:	Wearing surface	Width:	6.6 m
Element type:		Height:	0 m
Sub-element:		Length:	3.6 m
Material:	Gravel	Count:	1
Location:		Total Quantity:	24 sqm
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:	None Recommended	Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

B-115

5th Sideroad NDR Lot 5 Culvert



North Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	5th Sideroad NDR Lot 5 Culvert	Site Number:	B-115
District:		Road Name:	5th Sideroad NDR
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	150
Structure Type:	Box Culvert Open Footing - Rigid	Overall Struct. Width:	17.6 m
Number of Spans:	1	Roadway Width:	6.8 m
Direction of Structure:	North-South	Total Deck Length:	5.35 m
GPS Coordinates (Degrees)		Span (s):	4.2 m
General	Latitude: 44.197291	Total Deck Area:	94 sq.m
	Longitude: -81.017880	Current Load Limit:	0

Inspection Data

Date of Inspection:	10-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	10
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 74

Next Inspection: 10-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1970	Contract Number When Built:	
Latest Biennial Inspection:	March 22, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	74	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from west.



Description: Barrel: Medium longitudinal crack with leachate staining and stalactite (1/2).



Description: Barrel: Medium longitudinal crack with leachate staining and stalactite (2/2).



Description: Inlet: Medium horizontal crack.



Description: S&W: Heavy flow at time of inspection causing stream to be wider than culvert.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-115"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="4.2"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.2"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="17.6"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="116"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Medium longitudinal crack with leachate staining and stalactite mid barrel.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-115"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="5.35"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.2"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="East Side"/>	Total Quantity:	<input type="text" value="3"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Medium horizontal crack.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-115"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="5.35"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.2"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="West Side"/>	Total Quantity:	<input type="text" value="3"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="B-115"/>
Element Name:	<input type="text" value="Wearing Surface"/>	Width:	<input type="text" value="6.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="5.35"/> m
Material:	<input type="text" value="Asphalt"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="36"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



2024 Jun 10 10:00 AM

Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-115"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-115"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Heavy flow at time of inspection causing stream to be wider than culvert. Heavy sedemant build up causing difficult to inspect thouroughly.



Element Inspection

Element Group:	Foundations	Site Number:	B-115
Element Name:	Foundation (below ground level)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	Cast-in-place Concrete	Count:	2
Location:	<input type="text"/>	Total Quantity:	2 each
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: 0 Good: 2 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/> 0		

General Comments:

No signs of settlement.

OSIM Biennial Inspection Report



Site Number:

B-120

10th Sideroad NDR Lot 10-11 Culvert



North Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	10th Sideroad NDR Lot 10-11 Culvert	Site Number:	B-120
District:		Road Name:	10th Sideroad
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	50
Structure Type:	CSP (arch)	Overall Struct. Width:	18 m
Number of Spans:	1	Roadway Width:	6.6 m
Direction of Structure:	North-South	Total Deck Length:	2.4 m
GPS Coordinates (Degrees)		Span (s):	2.4 m
General	Latitude: 44.282322	Total Deck Area:	43 sq.m
	Longitude: -81.016020	Current Load Limit:	0

Inspection Data

Date of Inspection:	13-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	20
Special Notes:	High water level at time of inspection. Culvert appears to be in good condition, maintained true shape.

Overall Inspection Summary

BCI: 75

Next Inspection: 13-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1981	Contract Number When Built:	
Latest Biennial Inspection:	March 22, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	75	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: Improper splice bolt pattern, no cracking noted.



Description: Barrel: Light corrosion at waterline.



Description: North barrel: View from west.



Description: North barrel: View from east.



Description: South barrel: View from east.



Element Inspection

Element Group:	Culverts	Site Number:	B-120
Element Name:	Barrels	Width:	2.4 m
Element type:		Height:	1.7 m
Sub-element:		Length:	18 m
Material:	Corrugated Steel	Count:	2
Location:		Total Quantity:	226 sqm
Environment:	Moderate	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:	None Recommended	Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:

Improper splice bolt pattern, no cracking noted. Light corrosion at waterline.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-120"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="2.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text" value="East Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-120"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="2.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text" value="West Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="B-120"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="6.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="2.4"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="16"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-120"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Embankments & Streams	Site Number:	B-120
Element Name:	Embankments	Width:	0 m
Element type:		Height:	0 m
Sub-element:		Length:	0 m
Material:		Count:	4
Location:		Total Quantity:	4 each
Environment:	Moderate	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:	None Recommended	Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

B-198

3rd Sideroad WGR, Lot 7/8



West Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	3rd Sideroad WGR, Lot 7/8	Site Number:	B-198
District:		Road Name:	3rd Sideroad WGR
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	100
Structure Type:	Box Culvert Open Footing - Simple	Overall Struct. Width:	6.7 m
Number of Spans:	1	Roadway Width:	6.1 m
Direction of Structure:	East-West	Total Deck Length:	8.5 m
GPS Coordinates (Degrees)		Span (s):	4.4 m
General	Latitude: 44.295568	Total Deck Area:	57 sq.m
	Longitude: -80.857768	Current Load Limit:	0

Inspection Data

Date of Inspection:	13-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	20
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 73	Next Inspection:	13-Jun-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:		Contract Number When Built:	
Latest Biennial Inspection:	March 27, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	73	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from south.



Description: Outlet: Medium to wide crack.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-198"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="4.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="6.7"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="58"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-198"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="8.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="North Side"/>	Total Quantity:	<input type="text" value="9"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-198"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="8.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="South Side"/>	Total Quantity:	<input type="text" value="5"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Medium to wide crack.



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="B-198"/>
Element Name:	<input type="text" value="Wearing Surface"/>	Width:	<input type="text" value="6.1"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="8.5"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="52"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-198"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Steep embankments.



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-198"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Stream dry at time of inspection.



Element Inspection

Element Group:	<input type="text" value="Foundations"/>	Site Number:	<input type="text" value="B-198"/>
Element Name:	<input type="text" value="Foundation (below ground level)"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

No signs of settlement.

OSIM Biennial Inspection Report



Site Number:

N-190

Helena St. Culvert, Helena St., Ayton



South Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Helena St. Culvert. Helena St., Avton	Site Number:	N-190
District:	Helena St., Avton	Road Name:	Helena St
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	150
Structure Type:	CSP (arch)	Overall Struct. Width:	15 m
Number of Spans:	1	Roadway Width:	6.5 m
Direction of Structure:	North-South	Total Deck Length:	4 m
GPS Coordinates (Degrees)		Span (s):	4 m
REVIEWED	Latitude: 44.052257	Total Deck Area:	60 sq.m
	Longitude: -80.922771	Current Load Limit:	0

Inspection Data

Date of Inspection:	31-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	21
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 75	Next Inspection:	31-Jul-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	0	Contract Number When Built:	
Latest Biennial Inspection:	September 6, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	75.2	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from east.



Description: Barrel: Minor deformations in barrel.



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="N-190"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="6.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="4"/> m
Material:	<input type="text" value="Asphalt"/>	Count:	<input type="text"/>
Location:	<input type="text" value="Over Barrel"/>	Total Quantity:	<input type="text" value="26"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-190"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.3"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-190"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.3"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-190"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.3"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="15"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="188"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

Minor deformations in barrel.



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-190"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-190"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	N-190
Element Name:	Foundation (below ground)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	1
Location:	<input type="text"/>	Total Quantity:	1
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

No signs of settlement.

OSIM Biennial Inspection Report



Site Number:

N-187

Sideroad 25, Conc. 10, Lot 25/26



South Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Sideroad 25, Conc. 10, Lot 25/26	Site Number:	N-187
District:	Sideroad 25, Conc. 10	Road Name:	Side Rd 25
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	150
Structure Type:	CSP (arch)	Overall Struct. Width:	18 m
Number of Spans:	1	Roadway Width:	6.6 m
Direction of Structure:	East-West	Total Deck Length:	4 m
GPS Coordinates (Degrees)		Span (s):	3.3 m
REVIEWED	Latitude: 44.062571	Total Deck Area:	72 sq.m
	Longitude: -80.878421	Current Load Limit:	0

Inspection Data

Date of Inspection:	31-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	23
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 75	Next Inspection:	31-Jul-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	0	Contract Number When Built:	
Latest Biennial Inspection:	September 7, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	75	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: Light corrosion along waterline.



Description: Barrel: View from west.



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="N-187"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="6.6"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="4"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text"/>
Location:	<input type="text" value="Over Barrel"/>	Total Quantity:	<input type="text" value="26"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-187"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="West"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-187"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="East"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-187"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="3.3"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="18"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="195"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

Light corrosion along waterline.



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-187"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection


Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-187"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	N-187
Element Name:	Foundation (below ground)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	1
Location:	<input type="text"/>	Total Quantity:	1
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

No signs of settlement.

OSIM Biennial Inspection Report



Site Number:

N-072

Varney Road Culvert, Concession 2, Lot 74



West Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Varney Road Culvert, Concession 2, Lot 7	Site Number:	N-072
District:	Varney Rd., Concession 2, Lot 74	Road Name:	Varney Rd
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	200
Structure Type:	Box Culvert Open Footing - Rigid	Overall Struct. Width:	13.1 m
Number of Spans:	1	Roadway Width:	6.8 m
Direction of Structure:	North-South	Total Deck Length:	6.8 m
GPS Coordinates (Degrees)		Span (s):	6.3 m
REVIEWED	Latitude: 44.13621	Total Deck Area:	89 sq.m
	Longitude: -80.813256	Current Load Limit:	0

Inspection Data

Date of Inspection:	30-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Rain
Temperature:	23
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 73	Next Inspection:	30-Jul-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1970	Contract Number When Built:	
Latest Biennial Inspection:	September 15, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	73.2	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Wearing surface: Severe alligator cracking throughout.



Description: Barrel: View from south.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-072"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="6.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="0"/>
Location:	<input type="text" value="West"/>	Total Quantity:	<input type="text" value="4"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="N-072"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="6.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="6.8"/> m
Material:	<input type="text" value="Asphalt"/>	Count:	<input type="text"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="46"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

Severe alligator cracking throughout. Road should be resurfaced.



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-072"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-072"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-072"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="6.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="13.1"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="0"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="126"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-072"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="6.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="0"/>
Location:	<input type="text" value="East"/>	Total Quantity:	<input type="text" value="4"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

B-121

5th Sideroad NDR Lot 5-6 Culvert



South Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	5th Sideroad NDR Lot 5-6 Culvert	Site Number:	B-121
District:		Road Name:	5th Sideroad
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	75
Structure Type:	CSP (arch)	Overall Struct. Width:	19 m
Number of Spans:	1	Roadway Width:	6.6 m
Direction of Structure:	North-South	Total Deck Length:	3.8 m
GPS Coordinates (Degrees)		Span (s):	3.8 m
General	Latitude: 44.267873	Total Deck Area:	72 sq.m
	Longitude: -81.037891	Current Load Limit:	0

Inspection Data

Date of Inspection:	13-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	20
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI:

Next Inspection:

Additional Investigation Required:	<input type="text"/>	Priority:	<input type="text"/>
Additional Investigation Cost:	<input type="text"/>		
Rehabilitation Needs:	<input type="text"/>		
Rehabilitation Timing:	<input type="text"/>		
Total Rehabilitation Budget Costings:	<input type="text"/>	Engineering Fee:	<input type="text"/>

Historical Data

Year Built:	1979	Contract Number When Built:	<input type="text"/>
Latest Biennial Inspection:	March 22, 2023	Latest Specialized Inspection:	<input type="text"/>
Latest Structure Rating:	74	Latest Structure Condition:	<input type="text"/>
RehabHistory:			
Regional Priority Number:	<input type="text"/>	Programmed Work Year:	<input type="text"/>
NatureOfProgramWork:			

Description: Barrel: View from east.



Description: Barrel: Improper splice bolt pattern, no cracking noted.



Description: Barrel: Light to medium rust along waterline.



Description: Barrel: Minor sag in mid barrel.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-121"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="3.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="19"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="161"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Improper splice bolt pattern, no cracking noted. Light to medium rust along waterline. Minor sag in mid barrel.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-121"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="3.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.7"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="East side"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Culverts	Site Number:	B-121
Element Name:	Outlet Components	Width:	3.8 m
Element type:		Height:	2.7 m
Sub-element:		Length:	0 m
Material:	Corrugated Steel	Count:	1
Location:	West Side	Total Quantity:	1 sqm
Environment:	Moderate	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:	None Recommended	Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Decks	Site Number:	B-121
Element Name:	Wearing surface	Width:	6.6 m
Element type:		Height:	0 m
Sub-element:		Length:	3.8 m
Material:	Gravel	Count:	1
Location:		Total Quantity:	25 sqm
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:	None Recommended	Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-121"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-121"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Steep embankments recommend protection.



OSIM Biennial Inspection Report



Site Number:

N-172

Concession 14, Lot 27



West Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Concession 14, Lot 27	Site Number:	N-172
District:	Concession 14	Road Name:	Concession Rd 14
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	150
Structure Type:	CSP (arch)	Overall Struct. Width:	10 m
Number of Spans:	1	Roadway Width:	6.6 m
Direction of Structure:	East-West	Total Deck Length:	4.4 m
GPS Coordinates (Degrees)		Span (s):	4.4 m
REVIEWED	Latitude: 44.092654	Total Deck Area:	44 sq.m
	Longitude: -80.878195	Current Load Limit:	0

Inspection Data

Date of Inspection:	31-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	23
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 75	Next Inspection:	31-Jul-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1979	Contract Number When Built:	
Latest Biennial Inspection:	September 6, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	75	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: Improper splice bolt pattern, no signs of cracking.



Description: Barrel: Light corrosion along waterline.



Description: Barrel: View from north.



Element Inspection

Element Group:	Decks	Site Number:	N-172
Element Name:	Wearing surface	Width:	6.6 m
Element type:		Height:	
Sub-element:		Length:	4.4 m
Material:	Gravel	Count:	
Location:	Over Barrel	Total Quantity:	29 sqm
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:		Estimated Cost:	
Quantity:			

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-172"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="4.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-172"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="4.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	Culverts	Site Number:	N-172
Element Name:	Barrels	Width:	4.4 m
Element type:		Height:	0 m
Sub-element:		Length:	10 m
Material:	Corrugated Steel	Count:	1
Location:		Total Quantity:	138 sqm
Environment:	Benian	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:		Estimated Cost:	
Quantity:			

General Comments:

Improper splice bolt pattern, no signs of cracking. Light corrosion along waterline.



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-172"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-172"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Foundations"/>	Site Number:	<input type="text" value="N-172"/>
Element Name:	<input type="text" value="Foundation (below ground)"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

No signs of settlement.

OSIM Biennial Inspection Report



Site Number:

N-179

Sideroad 20, Conc. 15, Lot 20/21



North Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Sideroad 20. Conc. 15. Lot 20/21	Site Number:	N-179
District:	Sideroad 20	Road Name:	Side Rd 20
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	100
Structure Type:	CSP (arch)	Overall Struct. Width:	18 m
Number of Spans:	1	Roadway Width:	6.6 m
Direction of Structure:	North-South	Total Deck Length:	3 m
GPS Coordinates (Degrees)		Span (s):	3 m
REVIEWED	Latitude: 44.099807	Total Deck Area:	54 sq.m
	Longitude: -80.91354	Current Load Limit:	0

Inspection Data

Date of Inspection:	30-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Rain
Temperature:	23
Special Notes:	Culvert is in good condition, showing no signs of structural distress. Minor top deformations in barrel.

Overall Inspection Summary

BCI: 73

Next Inspection: 30-Jul-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1985	Contract Number When Built:	
Latest Biennial Inspection:	September 6, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	73.4	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: Minor deformations.



Description: Barrel: View from west.



Element Inspection

Element Group:	Decks	Site Number:	N-179
Element Name:	Wearing surface	Width:	6.6 m
Element type:		Height:	
Sub-element:		Length:	3 m
Material:	Gravel	Count:	
Location:	Over Barrel	Total Quantity:	20 sqm
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:		Estimated Cost:	
Quantity:			

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-179"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="3"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

Recommend remove vegetation.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-179"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="3"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-179"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="3"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="18"/> m
Material:	<input type="text" value="Corrugated Steel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="170"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>


Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

Minor deformations.



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-179"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-179"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	N-179
Element Name:	Foundation (below ground)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	1
Location:	<input type="text"/>	Total Quantity:	1
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: 0 Good: 1 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

No signs of settlement.

OSIM Biennial Inspection Report



Site Number:

B-113

3rd Sideroad WGR Lot 8 Concession 3 WGR Culvert



East Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	3rd Sideroad WGR Lot 8 Concession 3 W	Site Number:	B-113
District:		Road Name:	Sideroad 3 WGR
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	50
Structure Type:	Box Culvert Open Footing - Simple	Overall Struct. Width:	11.6 m
Number of Spans:	1	Roadway Width:	7 m
Direction of Structure:	East-West	Total Deck Length:	5.4 m
GPS Coordinates (Degrees)		Span (s):	4.9 m
General	Latitude: 44.291843	Total Deck Area:	63 sq.m
	Longitude: -80.892863	Current Load Limit:	0

Inspection Data

Date of Inspection:	13-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	20
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 74

Next Inspection: 13-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1960	Contract Number When Built:	
Latest Biennial Inspection:	March 27, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	74	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from north.



Description: Inlet: Medium cracking at construction joints, possible sign of inward rotation.



Description: Outlet: Medium cracking and shallow delaminations at construction joints.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-113"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="4.9"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.5"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="11.6"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="92"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-113"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="4.9"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.5"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="North Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Medium cracking at construction joints, possible sign of inward rotation. No signs of movement since last inspection, continue to monitor for further movement.



Element Inspection

Element Group:	Culverts	Site Number:	B-113
Element Name:	Outlet Components	Width:	4.9 m
Element type:		Height:	1.5 m
Sub-element:		Length:	0 m
Material:	Cast-in-place Concrete	Count:	1
Location:	South Side	Total Quantity:	2 sqm
Environment:	Moderate	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Medium cracking and shallow delaminations at construction joints, possible sign of inward rotation. No signs of movement since last inspection, continue to monitor for further movement.



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-113"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-113"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	B-113
Element Name:	Foundation (below ground level)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	Cast-in-place Concrete	Count:	<input type="text"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text"/> each
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: 0 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/> 0		

General Comments:

No signs of settlement.

OSIM Biennial Inspection Report



Site Number:

N-183

10th Sideroad, Conc. 5, Lot 10/11



South Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	10th Sideroad, Conc. 5, Lot 10/11	Site Number:	N-183
District:	10th Sideroad, Conc. 5 Lot 10/11	Road Name:	Side Rd 10
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	150
Structure Type:	Box Culvert Open Footing - Simple	Overall Struct. Width:	9 m
Number of Spans:	1	Roadway Width:	6.2 m
Direction of Structure:	North-South	Total Deck Length:	4 m
GPS Coordinates (Degrees)		Span (s):	3.5 m
REVIEWED	Latitude: 44.004448	Total Deck Area:	36 sq.m
	Longitude: -80.941749	Current Load Limit:	0

Inspection Data

Date of Inspection:	30-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	23
Special Notes:	Culvert is in good condition, showing no signs of structural distress. Possible wall inward rotation, monitor.

Overall Inspection Summary

BCI: 73	Next Inspection:	30-Jul-26
Additional Investigation Required:	Monitor Further Movement	Priority: Medium
Additional Investigation Cost:		
Rehabilitation Needs:		
Rehabilitation Timing:		
Total Rehabilitation Budget Costings:		Engineering Fee:

Historical Data

Year Built:	0	Contract Number When Built:	
Latest Biennial Inspection:	September 6, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	73.4	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Inlet: Minor separation on outside of construction joint, possible sign of slight wall rotation.



Description: Barrel: Shallow delamination throughout.



Description: Barrel: View from west.



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="N-183"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="6.2"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="4"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text"/>
Location:	<input type="text" value="Over Barrel"/>	Total Quantity:	<input type="text" value="25"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-183"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="3.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="East"/>	Total Quantity:	<input type="text" value="4"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

Minor seperation on outside of construction joint, possible sign of slight wall rotation, continue to monitor.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-183"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="3.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="West"/>	Total Quantity:	<input type="text" value="4"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-183"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="3.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.4"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="9"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="57"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

Shallow delamination throughout.



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-183"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-183"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	N-183
Element Name:	Foundation (below ground)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	2
Location:	<input type="text"/>	Total Quantity:	2
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

Cracking in top of walls indication of possible wall inward rotation.



N-163

Letter Breen Rd. Culvert, Letter Breen Road, Conc. 2, Lot 5



East Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Letter Breen Rd. Culvert, Letter Breen Roa	Site Number:	N-163
District:	Letter Breen Rd	Road Name:	Letterbreen Rd
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	250
Structure Type:	CSP (arch)	Overall Struct. Width:	14 m
Number of Spans:	3	Roadway Width:	5.6 m
Direction of Structure:	East-West	Total Deck Length:	15 m
GPS Coordinates (Degrees)		Span (s):	2.8 m
REVIEWED	Latitude: 44.016426	Total Deck Area:	210 sq.m
	Longitude: -80.797838	Current Load Limit:	0

Inspection Data

Date of Inspection:	31-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	23
Special Notes:	Culvert is in fair to good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 74	Next Inspection:	31-Jul-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1985	Contract Number When Built:	
Latest Biennial Inspection:	September 7, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	73.6	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: Light to medium corrosion in base region.



Description: Barrel: View from north.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-163"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="3"/>
Location:	<input type="text" value="South"/>	Total Quantity:	<input type="text" value="3"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text" value="Routine"/>
Maint needs:	<input type="text" value="Remove vegetation"/>	Maint. Time Period:	<input type="text" value="2 Year"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Recommend removing vegetation.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-163"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="3"/>
Location:	<input type="text" value="North"/>	Total Quantity:	<input type="text" value="3"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="N-163"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="N-163"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-163"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="2.8"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="14"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="3"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="250"/> sqm
Environment:	<input type="text" value="Benian"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Only middle barrel functioning properly as other two barrels are filled with sediment. Light to medium corrosion in base region.



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="N-163"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="5.6"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="15"/> m
Material:	<input type="text" value="Asphalt"/>	Count:	<input type="text" value="0"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="84"/> sqm
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

D-101

Garafraxa Street



South Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Garafraxa Street	Site Number:	D-101
District:		Road Name:	HWY 6
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	4300
Structure Type:	Box Culvert Open Footing - Rigid	Overall Struct. Width:	11.6 m
Number of Spans:	1	Roadway Width:	8 m
Direction of Structure:	North-South	Total Deck Length:	3 m
GPS Coordinates (Degrees)		Span (s):	1.2 m
REVIEWED	Latitude: 44.173217	Total Deck Area:	35 sq.m
	Longitude: -80.817589	Current Load Limit:	0

Inspection Data

Date of Inspection:	30-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Rain
Temperature:	23
Special Notes:	Culvert is in excellent condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 100

Next Inspection: 30-Jul-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	2021	Contract Number When Built:	
Latest Biennial Inspection:	September 15, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	100	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from east.



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="D-101"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="7"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="1.25"/> m
Material:	<input type="text" value="Asphalt"/>	Count:	<input type="text"/>
Location:	<input type="text" value="Over Barrel"/>	Total Quantity:	<input type="text" value="9"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="D-101"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="1.2"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0.6"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="East"/>	Total Quantity:	<input type="text" value="25"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="D-101"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="1.2"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0.6"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="West"/>	Total Quantity:	<input type="text" value="18"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="D-101"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="1.2"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0.6"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="11.6"/> m
Material:	<input type="text" value="Pre-cast Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="28"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="D-101"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="D-101"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	D-101
Element Name:	Foundation (below ground)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	2
Location:	<input type="text"/>	Total Quantity:	2
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: 0 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

No signs of settlement.

Element Inspection

Element Group:	<input type="text" value="Sidewalks/ curbs"/>	Site Number:	<input type="text" value="D-101"/>
Element Name:	<input type="text" value="Curbs"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="3"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="6"/> m
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (m):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Barriers"/>	Site Number:	<input type="text" value="D-101"/>
Element Name:	<input type="text" value="Railing systems"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="3"/> m
Material:	<input type="text" value="Steel"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="6"/> m
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (m):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Sidewalks/ curbs"/>	Site Number:	<input type="text" value="D-101"/>
Element Name:	<input type="text" value="Sidewalks"/>	Width:	<input type="text" value="1.5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="3"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="6"/>
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

G-048

Concession 4, Lot 10/11, Baptist Church Rd Culvert



North Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Concession 4, Lot 10/11, Baptist Church R	Site Number:	G-048
District:		Road Name:	Baptist Church Road
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	250
Structure Type:	Box Culvert Open Footing - Simple	Overall Struct. Width:	19 m
Number of Spans:	1	Roadway Width:	6.7 m
Direction of Structure:	North-South	Total Deck Length:	5.9 m
GPS Coordinates (Degrees)		Span (s):	4.9 m
General	Latitude: 44.222339	Total Deck Area:	112 sq.m
	Longitude: -80.724974	Current Load Limit:	0

Inspection Data

Date of Inspection:	12-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	21
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 75

Next Inspection: 12-Jun-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1967	Contract Number When Built:	
Latest Biennial Inspection:	March 24, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	75	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from west.



Description: Barrel: Light to medium vertical cracks with leachate staining.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-048"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="4.9"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="3.1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="19"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="211"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Light to medium vertical cracks with leachate staining.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-048"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="5.9"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="3.1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="East Side"/>	Total Quantity:	<input type="text" value="32"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="G-048"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="5.9"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="3.1"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="West Side"/>	Total Quantity:	<input type="text" value="6"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Decks	Site Number:	G-048
Element Name:	Wearing Surface	Width:	6.7 m
Element type:		Height:	0 m
Sub-element:		Length:	5.9 m
Material:	Asphalt	Count:	1
Location:		Total Quantity:	40 sqm
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:		Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:		Estimated Cost:	
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-048"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="G-048"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	G-048
Element Name:	Foundation (below ground level)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text"/> each
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: 0 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/> 0		

General Comments:

No signs of stettlement.



N-165

Camp Creek Culvert, Normanby-Bentinck Townline, Conc.



West Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Camp Creek Culvert, Normanby-Bentinck	Site Number:	N-165
District:	Normanby-Bentinck TL, 0.7 km West of Hi	Road Name:	Normanby-Bentinck Townline
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	0
Structure Type:	Box Culvert Open Footing - Rigid	Overall Struct. Width:	19 m
Number of Spans:	1	Roadway Width:	6.5 m
Direction of Structure:	North-South	Total Deck Length:	6.8 m
GPS Coordinates (Degrees)		Span (s):	5 m
REVIEWED	Latitude: 44.14812	Total Deck Area:	129 sq.m
	Longitude: -80.823342	Current Load Limit:	0

Inspection Data

Date of Inspection:	30-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Rain
Temperature:	23
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: **75**

Next Inspection: 30-Jul-26

Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1985	Contract Number When Built:	
Latest Biennial Inspection:	September 15, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	75	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from south.



Element Inspection

Element Group:	Decks	Site Number:	N-165
Element Name:	Wearing surface	Width:	6.5 m
Element type:		Height:	
Sub-element:		Length:	6.8 m
Material:	Gravel	Count:	
Location:	Over Barrel	Total Quantity:	44 sqm
Environment:	Severe	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	
Maint needs:		Maint. Time Period:	

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:		Unit Cost:	
Rehab time period:		Estimated Cost:	
Quantity:			

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-165"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0.8"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="North"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-165"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0.8"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="South"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-165"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="5"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0.8"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="19"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="125"/> sqm
Environment:	<input type="text" value="Benian"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-165"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-165"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	N-165
Element Name:	Foundation (below ground)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	2
Location:	<input type="text"/>	Total Quantity:	2
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: 0 **Good:** 2 **Fair:** 0 **Poor:** 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

No signs of settlement.

Element Inspection

Element Group:	<input type="text" value="Barriers"/>	Site Number:	<input type="text" value="N-165"/>
Element Name:	<input type="text" value="Railing systems"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text" value="Post and Cable"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="6.8"/> m
Material:	<input type="text" value="Hybrid"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="14"/> m
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (m):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

N-071

Pfeffer Culvert, Concession 2, Lot 70/71



West Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	Pfeffer Culvert, Concession 2, Lot 70/71	Site Number:	N-071
District:	Pfeffer, Road 71	Road Name:	Rd 71
County:	Grey County	Owner:	West Grey
Township:		Skew:	0
Bridge or Culvert:	Culvert	AADT:	250
Structure Type:	Box Culvert - Rigid	Overall Struct. Width:	24 m
Number of Spans:	1	Roadway Width:	7.3 m
Direction of Structure:	North-South	Total Deck Length:	5.3 m
GPS Coordinates (Degrees)		Span (s):	4.9 m
REVIEWED	Latitude: 43.981504	Total Deck Area:	127 sq.m
	Longitude: -80.811391	Current Load Limit:	0

Inspection Data

Date of Inspection:	31-Jul-24
Name of Inspector:	Andrew Burgess, P.Eng. & Joel Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Sunny
Temperature:	23
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 75	Next Inspection:	31-Jul-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:	1977	Contract Number When Built:	
Latest Biennial Inspection:	September 7, 2022	Latest Specialized Inspection:	
Latest Structure Rating:	75	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from north.



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="N-071"/>
Element Name:	<input type="text" value="Wearing surface"/>	Width:	<input type="text" value="7.3"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="5.3"/> m
Material:	<input type="text" value="Asphalt"/>	Count:	<input type="text"/>
Location:	<input type="text" value="Over Barrel"/>	Total Quantity:	<input type="text" value="39"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-071"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="4.9"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.65"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="South"/>	Total Quantity:	<input type="text" value="5"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-071"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="4.9"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.65"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="North"/>	Total Quantity:	<input type="text" value="5"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="N-071"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="4.9"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="2.65"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="24"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="362"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-071"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments and Streams"/>	Site Number:	<input type="text" value="N-071"/>
Element Name:	<input type="text" value="Streams & waterways"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/>
Environment:	<input type="text"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text" value="None"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:



Element Inspection

Element Group:	Foundations	Site Number:	N-071
Element Name:	Foundation (below ground)	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	2
Location:	<input type="text"/>	Total Quantity:	2
Environment:	Benign	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	None	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data:

Exec: 0 Good: 2 Fair: 0 Poor: 0

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text"/>		

General Comments:

No signs of settlement.

Element Inspection

Element Group:	<input type="text" value="Barriers"/>	Site Number:	<input type="text" value="N-071"/>
Element Name:	<input type="text" value="Railing systems"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text" value="Flexi beam with timber posts"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="5.3"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="11"/> m
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (m):
Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text" value="None Recommended"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



OSIM Biennial Inspection Report



Site Number:

B-195

6Conc. 4 NDR, Lot 26



West Approach



Burgess Engineering Inc

27-Aug-24

Inventory Data

Structure Name:	6Conc. 4 NDR, Lot 26	Site Number:	B-195
District:		Road Name:	Concession 4 NDR
County:	Grey County	Owner:	West Grey
Township:	West Grey	Skew:	0
Bridge or Culvert:	Culvert	AADT:	250
Structure Type:	Box Culvert Open Footing - Simple	Overall Struct. Width:	14 m
Number of Spans:	1	Roadway Width:	6.6 m
Direction of Structure:	East-West	Total Deck Length:	3 m
GPS Coordinates (Degrees)		Span (s):	2.4 m
General	Latitude: 44.207934	Total Deck Area:	42 sq.m
	Longitude: -80.915086	Current Load Limit:	0

Inspection Data

Date of Inspection:	10-Jun-24
Name of Inspector:	A. Burgess P.Eng. & J. Ziegler CET
Equipment Used:	Sounding hammer, measuring equipment, GPS
Weather Conditions:	Cloudy
Temperature:	12
Special Notes:	Culvert is in good condition, showing no signs of structural distress.

Overall Inspection Summary

BCI: 74	Next Inspection:	10-Jun-26	
Additional Investigation Required:		Priority:	
Additional Investigation Cost:			
Rehabilitation Needs:			
Rehabilitation Timing:			
Total Rehabilitation Budget Costings:		Engineering Fee:	

Historical Data

Year Built:		Contract Number When Built:	
Latest Biennial Inspection:	March 23, 2023	Latest Specialized Inspection:	
Latest Structure Rating:	74	Latest Structure Condition:	
RehabHistory:			
Regional Priority Number:		Programmed Work Year:	
NatureOfProgramWork:			

Description: Barrel: View from north.



Description: Barrel: Shallow spalling with exposed reinforcing.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-195"/>
Element Name:	<input type="text" value="Barrels"/>	Width:	<input type="text" value="2.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.3"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="14"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="70"/> sqm
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Shallow spalling with exposed reinforcing.



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-195"/>
Element Name:	<input type="text" value="Inlet Components"/>	Width:	<input type="text" value="2.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.3"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="South Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Culverts"/>	Site Number:	<input type="text" value="B-195"/>
Element Name:	<input type="text" value="Outlet Components"/>	Width:	<input type="text" value="2.4"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="1.3"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text" value="Cast-in-place Concrete"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text" value="North Side"/>	Total Quantity:	<input type="text" value="2"/> sqm
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Decks"/>	Site Number:	<input type="text" value="B-195"/>
Element Name:	<input type="text" value="Wearing Surface"/>	Width:	<input type="text" value="6.6"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="3"/> m
Material:	<input type="text" value="Gravel"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="20"/> sqm
Environment:	<input type="text" value="Severe"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (sqm):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-195"/>
Element Name:	<input type="text" value="Embankments"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="4"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="4"/> each
Environment:	<input type="text" value="Moderate"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

Steep embankments.



Element Inspection

Element Group:	<input type="text" value="Embankments & Streams"/>	Site Number:	<input type="text" value="B-195"/>
Element Name:	<input type="text" value="Streams and Waterways"/>	Width:	<input type="text" value="0"/> m
Element type:	<input type="text"/>	Height:	<input type="text" value="0"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text" value="0"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="1"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="1"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:



Element Inspection

Element Group:	<input type="text" value="Foundations"/>	Site Number:	<input type="text" value="B-195"/>
Element Name:	<input type="text" value="Foundation (below ground level)"/>	Width:	<input type="text"/> m
Element type:	<input type="text"/>	Height:	<input type="text"/> m
Sub-element:	<input type="text"/>	Length:	<input type="text"/> m
Material:	<input type="text"/>	Count:	<input type="text" value="2"/>
Location:	<input type="text"/>	Total Quantity:	<input type="text" value="2"/> each
Environment:	<input type="text" value="Benign"/>	Not inspected:	<input type="checkbox"/>
Perform. deficiencies:	<input type="text"/>	Maintenance Type:	<input type="text"/>
Maint needs:	<input type="text"/>	Maint. Time Period:	<input type="text"/>

Condition Data (each):

Exec: Good: Fair: Poor:

Rehab Needs:	<input type="text"/>	Unit Cost:	<input type="text"/>
Rehab time period:	<input type="text"/>	Estimated Cost:	<input type="text"/>
Quantity:	<input type="text" value="0"/>		

General Comments:

No signs of settlement.



2024 Bridge Condition Index (BCI)

BCI	Years Left	Site #	Structure Name	Road Name	Structure Type	Deck Area (m ²)	Status
28.3	0	N-189	+Sideroad 25, Conc. 13, Lot 26	Side Rd 25	Box Culvert Open Footing - Simple	32	Closed
44.3	0	G-038	Concession 2 & 3N, Lot 6	Northline Road	Concrete Arch	87	Closed
48.7	0	G-033	Concession 9, Lot 9, Traverston Bridge	Traverston Road	Through Truss w/ Concrete Deck	209	Closed
51.4	0	B-020	Concession 2 & 3, Kennedy Bridge	Concession 2 NDR	Pony Truss w/ Concrete Deck	139	Closed
57.8	0	B-025	Hudson Bridge, Concession 3 SDR, Lot 21, 10th Sideroad SDR	Normanby-Bentinck Townline	Pony Truss w/ Timber Deck	153	Closed
57.8	0	N-051	Concession 17 & 18, Lot 15 Bridge	Concession 18	Pony Truss w/ Timber Deck	128	Closed
63.2	0	N-055	Hampden Bridge, Concession 17, Lot 20/21	Side Rd 20	Pony Truss w/ Timber Deck	136	Closed
67.4	0	N-070	Concession 2, Lot 74	Concession Rd 2 WGR	Pony Truss w/ Timber Deck	190	Closed
36.5	0	EG-001	Stonehill Road Culvert	Stonehill Road	CSP (round)	8	Open
46.8	1	N-184	Sideroad 25, Conc. 8, Lot 25/26	Side Rd 25	Box Culvert Open Footing - Simple	33	Open
50.1	1	B-003	Concession 6 & 7, Lot 18 Bridge	Concession 6	Concrete Rigid Frame	113	Open
51.2	1	G-044	Concession 2-3N, Lot 32	N Line	Concrete Arch	102	Open
54.1	4	N-188	Sideroad 25, Conc. 12, Lot 25/26	Side Rd 25	Box Culvert Open Footing - Simple	26	Open
57.7	1	G-037	Concession 2 & 3, Lot 6	North Line	Concrete Rigid Frame	78	Open
61.8	2	G-132	Baseline, 0.3 km North of Grey Rd 4 Culvert	Baseline	CSP (arch)	58	Open
63.8	6	B-008	Concession 12, Lot 32 & 13, 3W Bridge	Baseline	Concrete Rigid Frame	61	Open
65.5	6	G-133	Southline Road, Concession 2 EGR, Lot 63-64	Southline	Box Culvert Open Footing - Simple	27	Open
66.9	10	B-196	Welbeck Rd Culvert	Welbeck Road	Box Culvert Open Footing - Simple	32	Open
67.4	8	N-185	Sideroad 25, Conc. 8, Lot 25/26	Side Rd 25	Box Culvert Open Footing - Simple	42	Open
67.4	9	B-001	Concession 12 & 13 NDR, Lot 3 Bridge	Concession 12	Concrete Rigid Frame	69	Open
67.5	12	G-040	Concession 4, Lot 12 & 13, Burkes Bridge	Concession 4	Pony Truss w/ Concrete Deck	107	Open
67.5	7	B-011	Concession 1W, Lot 3 & 4 Bridge	Sideroad 3 WGR	Concrete Rigid Frame	57	Open
68.5	2	N-061	Concession 13/14, Lot 30	Concession Rd 14	Pony Truss w/ Timber Deck	88	Open
68.7	12	B-009	Concession 3W, Lot 14 & 15 Bridge	Welbeck Road	Concrete Rigid Frame	95	Open
69.6	12	G-041	Concession 4, Burkes Overflow Bridge	Concession 4	Concrete Rigid Frame	70	Open
69.7	8	N-060	Concession 11/12, Lot 30	Concession Rd 12	Box Culvert Open Footing - Simple	49	Open
70.0	8	N-058	Concession 11/12, Lot 30	Concession Rd 12	Concrete T-Beam	75	Open
70.1	13	B-006	Concession 11, Lot 25 & 26 Bridge	Mulock Road	Concrete Rigid Frame	67	Open
71.1	22	B-021	Concession 2 & 3, Overflow Structure to Kennedy	Concession 2 NDR	Concrete Rigid Frame	91	Open
71.1	16	N-059	Concession 11/12, Lot 30	Concession Rd 12	Concrete T-Beam	68	Open
71.3	18	B-119	Concession 14 NDR Lot 3 Culvert	Concession 14 NDR	Box Culvert Open Footing - Simple	40	Open
71.7	11	B-007	Concession 12, Lot 30 & 31 Bridge	30th Sideroad NDR	Timber Deck w/ Steel Beams	54	Open
71.7	14	N-056	Concession 15/16, Lot 27	Concession Rd 16	Pony Truss w/ Timber Deck	127	Open
71.7	21	B-005	Concession 10 & 11, Lot 25 Bridge	Concession 10	Concrete Rigid Frame	61	Open



2024 Bridge Condition Index (BCI)

BCI	Years Left	Site #	Structure Name	Road Name	Structure Type	Deck Area (m ²)	Status
72.0	28	B-026	Mulock Road Bridge, Concession 2 SDR, Lot 50/51, Mulock Road	Mulock Rd	Concrete Rigid Frame	106	Open
72.1	18	G-031	Concession 2 & 3E, Lot 28 Bridge	Concession 2	Concrete Rigid Frame	131	Open
72.1	18	B-004	Concession 8 & 9, NDR, Lot 18 Bridge	Concession 8	Concrete Rigid Frame	60	Open
72.1	18	B-104	Baseline Rd. at Sideroad 18 Culvert	Baseline Rd	CSP (arch)	96	Open
72.2	30	B-107	Concession 4 NDR Lot 3 Culvert	Concession 4	Box Culvert Open Footing - Rigid	54	Open
72.6	27	B-198	3rd Sideroad WGR, Lot 7/8	3rd Sideroad WGR	Box Culvert Open Footing - Simple	57	Open
72.7	28	B-027	Concession 3 SDR, Lot 57, Concession 2 SDR	Concession Rd 2 SDR	Concrete Rigid Frame	132	Open
72.8	32	N-054	Ford's Bridge, Concession 15/16, Lot 7	Concession Rd 16	Concrete Rigid Frame	359	Open
72.9	22	B-015	Concession 5, Sills (Overflow)	Mulock Road	Concrete Rigid Frame	82	Open
72.9	33	N-067	Concession 2/3, Lot 63	Concession Rd 2 WGR	Concrete Arch	57	Open
73.0	21	B-114	Old Bridge Rd South Culvert	Old Bridge Road	Box Culvert Open Footing - Simple	50	Open
73.0	18	G-046	Concession 2 & 3N, Lot 43, McQuarrie Bridge	NorthLine	Pony Truss w/ Concrete Deck	145	Open
73.0	21	B-013	Concession 3W, Jelinski Bridge	Baseline	Box Culvert Open Footing - Simple	58	Open
73.2	26	N-072	Varney Road Culvert, Concession 2, Lot 74	Varney Rd	Box Culvert Open Footing - Rigid	89	Open
73.4	26	N-179	Sideroad 20, Conc. 15, Lot 20/21	Side Rd 20	CSP (arch)	54	Open
73.4	22	G-035	Concession 2 & 3W, Lot 100, West Back Line Road	West Back Line	Concrete Arch	222	Open
73.4	22	N-183	10th Sideroad, Conc. 5, Lot 10/11	Side Rd 10	Box Culvert Open Footing - Simple	36	Open
73.5	23	B-195	6Conc. 4 NDR, Lot 26	Concession 4 NDR	Box Culvert Open Footing - Simple	42	Open
73.7	18	N-163	Letter Breen Rd. Culvert, Letter Breen Road, Conc. 2, Lot 55/56	Letterbreen Rd	CSP (arch)	210	Open
73.7	16	G-154	Traverston Road, 1.4 km S of Concession 12 Culvert	Traverston Road	CSP (arch)	62	Open
73.8	26	B-019	Concession 2 & 3, Lot 35 Bridge	Concession 2 NDR	Concrete Rigid Frame	121	Open
73.9	24	B-113	3rd Sideroad WGR Lot 8 Concession 3 WGR Culvert	Sideroad 3 WGR	Box Culvert Open Footing - Simple	63	Open
73.9	25	B-018	Concession 2 & 3W, Lot 42 Bridge	Concession 2 WGR	Concrete Rigid Frame	193	Open
74.0	21	G-039	Concession 4, Lot 13, Baptist Church Road Bridge	Baptist Church Road	Pony Truss w/ Concrete Deck	176	Open
74.0	56	N-064	Diepel Bridge, Concession 7, Lot 5/6	Side Rd 5	Concrete Rigid Frame	95	Open
74.1	14	B-017	Concession 4 & 5, Lot 29 Bridge	Concession 4	Through Truss w/ Concrete Deck	187	Open
74.2	20	B-105	Concession 4 NDR Lot 30 Culvert	Concession 4	CSP (arch)	185	Open
74.2	28	G-032	Concession 8 & 9, Lot 5 Bridge	Concession 8	Concrete Rigid Frame	133	Open
74.3	58	N-065	Riest Bridge, Concession 5/6, Lot 9	Concession Rd 6	Concrete Deck w/ Pre-stressed Beams	227	Open
74.4	24	B-121	5th Sideroad NDR Lot 5-6 Culvert	5th Sideroad	CSP (arch)	72	Open
74.4	41	G-047	Saugeen River Bridge, Concession 2-3N, Lot 47	N Line	Concrete Deck w/ Steel Beams	116	Open
74.4	27	B-115	5th Sideroad NDR Lot 5 Culvert	5th Sideroad NDR	Box Culvert Open Footing - Rigid	94	Open
74.4	20	B-118	Concession 14 NDR Lot 11 Culvert	Concession 14	CSP (arch)	38	Open
74.5	28	B-012	Concession 1W, Lot 6 & 7 Bridge	Welbeck Road	Concrete Rigid Frame	80	Open



2024 Bridge Condition Index (BCI)

BCI	Years Left	Site #	Structure Name	Road Name	Structure Type	Deck Area (m ²)	Status
74.5	38	N-171	Concession 14, Lot 20	Concession Rd 14	CSP (arch)	42	Open
74.6	46	B-014	Concession 4 & 5, Roy Hopkins Bridge	Concession 4	Concrete Deck w/ Pre-stressed Beams	624	Open
74.6	53	N-069	Pfeffer Bridge, Concession 2, Lot 70/71	Rd 71	Concrete Deck w/ Pre-stressed Beams	471	Open
74.6	46	B-022	Concession 3, Bailey Bridge	Allan Park Road	Concrete Deck w/ Pre-stressed Beams	264	Open
74.7	38	N-063	Glasser Bridge, Concession 7/8, Lot 3	Concession Rd 8	Concrete Rigid Frame	164	Open
74.7	58	B-023	Herd Bridge, Concession 1 SDR, Lot 40/41	Allen Park Road	Concrete Rigid Frame	134	Open
74.7	28	G-048	Concession 4, Lot 10/11, Baptist Church Rd Culvert	Baptist Church Road	Box Culvert Open Footing - Simple	112	Open
74.8	30	G-148	Concession 6, West of Glenelg Rd 23 Culvert	Concession 6	Box Culvert Open Footing - Rigid	87	Open
74.8	58	N-062	Concession 13/14, Lot 30	Concession Rd 14	Concrete Rigid Frame	102	Open
74.8	29	B-010	Concession 2 & 3W, Long Swamp Bridge	Concession 2	Concrete Rigid Frame	82	Open
74.8	33	N-050	Concession 17/18, Lot 1	Concession Road 18 Extension	Concrete Deck w/ Steel Beams	198	Open
74.8	29	G-030	Concession 2 & 3E, Lot 3	Concession 2	Box Culvert Open Footing - Rigid	71	Open
74.9	58	N-052	Concession 2/3, Lot 5	Concession Rd 2 WGR	Concrete Rigid Frame	106	Open
74.9	53	N-068	Concession 3, Lot 63/64	63 Rd	Concrete Rigid Frame	120	Open
74.9	23	N-199	Culvert, Concession 12, Lot 26	Concession Rd 12	CSP (arch)	57	Open
74.9	46	B-016	Concession 5, Silks Bridge	Mulock Road	Concrete Deck w/ Pre-stressed Beams	171	Open
74.9	41	G-045	Concession 2 & 3N, Lot 33, Northline Rd Bridge	North Line	Concrete Deck w/ Steel Beams	105	Open
74.9	30	P-101	Durham Pedestrian Bridge	George St East	Timber Deck w/ Timber Beams	505	Open
74.9	56	G-043	Glenelg Centre Bridge, Concession 5, Lot 17	Concession Rd 4	Concrete Deck w/ Pre-stressed Beams	373	Open
75.0	33	N-066	Concession 5/6, Lot 19	Concession Rd 6	Concrete Rigid Frame	328	Open
75.0	46	B-002	Concession 4 & 5, Styx View Bridge	Concession 4	Concrete Deck w/ Pre-stressed Beams	249	Open
75.0	48	N-057	Kreller Bridge, Concession 11/12, Lot 9	Concession Rd 12	Concrete Deck w/ Pre-stressed Beams	485	Open
75.0	21	B-120	10th Sideroad NDR Lot 10-11 Culvert	10th Sideroad	CSP (arch)	43	Open
75.0	43	N-053	Concession 15/16, Lot 1	Concession Rd 12 E	Concrete Deck w/ Steel Beams	245	Open
75.0	53	N-071	Pfeffer Culvert, Concession 2, Lot 70/71	Rd 71	Box Culvert - Rigid	127	Open
75.0	48	N-165	Camp Creek Culvert, Normanby-Bentinck Townline, Conc. 1, Lot 1	Normanby-Bentinck Townline	Box Culvert Open Footing - Rigid	129	Open
75.0	26	N-172	Concession 14, Lot 27	Concession Rd 14	CSP (arch)	44	Open
75.0	36	N-178	Sideroad 20, Conc. 13, Lot 20/21	Side Rd 20	CSP (arch)	41	Open
75.0	18	N-187	Sideroad 25, Conc. 10, Lot 25/26	Side Rd 25	CSP (arch)	72	Open
75.0	63	P-102	Neustadt Pedestrian Bridge	Walking Trail	Pony Truss w/ Timber Deck	36	Open
75.2	48	N-190	Helena St. Culvert, Helena St., Ayton	Helena St	CSP (arch)	60	Open
86.5	50	D-001	Garafraxa Street Culvert, Durham	HWY 6	Concrete Rigid Frame	313	Open
98.4	71	G-197	Concession 8/9, Lot 10	Concession 8	CSP (round)	54	Open
99.5	66	G-126	Baptist Church Rd, Concession 8 Culvert	Baptist Church Rd	CSP (arch)	58	Open
99.6	46	B-112	Concession 2 WGR Lot 3 Culvert	Concession 2	CSP (arch)	43	Open



2024 Bridge Condition Index (BCI)

BCI	Years Left	Site #	Structure Name	Road Name	Structure Type	Deck Area (m ²)	Status
100.0	73	B-028	Concession 2 & 3W, Lantz Bridge	Concession 2 WGR	Timber Deck w/ Timber Beams	208	Open
100.0	73	D-101	Garafraxa Street	HWY 6	Box Culvert Open Footing - Rigid	35	Open

2024 Maintenance Needs



Site #	Structure Name	Road Name	Element Name	Element Group	Needs Type	Maintenance Needs	Time Period (yrs)
B-001	Concession 12 & 13 NDR, Lot 3 Bridge	Concession 12	Approaches	Curbs	Routine	Bridge cleaning	2
			Decks	Drainage System	Structural	Install/extend drain pipes	2
			Abutments	Wingwalls	Routine	Bridge cleaning	2
B-004	Concession 8 & 9, NDR, Lot 18 Bridge	Concession 8	Decks	Drainage System	Structural	Install/extend drain pipes	1
B-005	Concession 10 & 11, Lot 25 Bridge	Concession 10	Decks	Drainage System	Structural	Install/extend drain pipes	2
B-006	Concession 11, Lot 25 & 26 Bridge	Mulock Road	Approaches	Wearing surface	Structural	Asphalt Repairs	1
			Decks	Wearing Surface	Structural	Asphalt Repairs	1
			Decks	Drainage system	Structural	Install/extend drain pipes	1
B-007	Concession 12, Lot 30 & 31 Bridge	30th Sideroad NDR	Accessories (Attachments and Signs)	Signs	Routine	Sign Repair	1
B-008	Concession 12, Lot 32 & 13, 3W Bridge	Baseline	Embankments & Streams	Embankments	Routine	Erosion control	1
B-010	Concession 2 & 3W, Long Swamp Bridge	Concession 2	Barriers	Barrier/Parapet Walls	Structural	Barrier/railing system repair	2
B-011	Concession 1W, Lot 3 & 4 Bridge	Sideroad 3 WGR	Barriers	Railing systems	Structural	Barrier/railing system repair	1
B-012	Concession 1W, Lot 6 & 7 Bridge	Welbeck Road	Decks	Wearing Surface	Structural	Asphalt Repairs	2
B-016	Concession 5, Sills Bridge	Mulock Road	Embankments & Streams	Embankments	Routine	Erosion control	2
B-017	Concession 4 & 5, Lot 29 Bridge	Concession 4	Barriers	Railing systems	Structural	Barrier/railing system repair	1
B-018	Concession 2 & 3W, Lot 42 Bridge	Concession 2 WGR	Barriers	Railing systems	Structural	Barrier/railing system repair	1
			Embankments & Streams	Embankments	Routine	Erosion control	2
B-019	Concession 2 & 3, Lot 35 Bridge	Concession 2 NDR	Decks	Wearing Surface	Routine	Bridge cleaning	1
B-021	Concession 2 & 3, Overflow Structure to Kennedy	Concession 2 NDR	Barriers	Railing Systems	Structural	Barrier/railing system repair	1
B-022	Concession 3, Bailey Bridge	Allan Park Road	Barriers	Railing Systems	Structural	Barrier/railing system repair	1
			Joints	Seals (strip)	Routine	Bridge cleaning	1
B-025	Hudson Bridge, Concession 3 SDR, Lot 21, 10th Sideroad SDR	Normanby-Bentinck Townline	Approaches	Railing system	Structural	Repair guide rail protection	1
			Decks	Wearing surface	Structural	Asphalt Repairs	1

2024 Maintenance Needs



Site #	Structure Name	Road Name	Element Name	Element Group	Needs Type	Maintenance Needs	Time Period (yrs)
B-027	Concession 3 SDR, Lot 57, Concession 2 SDR	Concession Rd 2 SDR	Sidewalks/curbs	Curbs	Routine	Bridge cleaning	2
B-104	Baseline Rd. at Sideroad 18 Culvert	Baseline Rd	Barriers	Railing systems	Structural	Barrier/railing system repair	2
B-105	Concession 4 NDR Lot 30 Culvert	Concession 4	Barriers	Railing systems	Structural	Barrier/railing system repair	2
B-107	Concession 4 NDR Lot 3 Culvert	Concession 4	Barriers	Railing Systems	Structural	Barrier/railing system repair	1
B-107	Concession 4 NDR Lot 3 Culvert	Concession 4	Embankments & Streams	Embankments	Routine	Erosion control	2
B-114	Old Bridge Rd South Culvert	Old Bridge Road	Decks	Wearing Surface	Structural	Asphalt Repairs	2
B-119	Concession 14 NDR Lot 3 Culvert	Concession 14 NDR	Barriers	Railing Systems	Structural	Barrier/railing system repair	1
			Barriers	Railing systems	Structural	Barrier/railing system repair	2
G-031	Cencession 2 & 3E, Lot 28 Bridge	Concession 2	Barriers	Railing Systems	Structural	Barrier/railing system repair	1
G-032	Concession 8 & 9, Lot 5 Bridge	Concession 8	Barriers	Railing systems	Structural	Barrier/railing system repair	2
			Barriers	Railing Systems	Structural	Barrier/railing system repair	2
G-037	Concession 2 & 3, Lot 6	North Line	Sidewalks/ curbs	Curbs	Routine	Bridge cleaning	1
G-038	Concession 2 & 3N, Lot 6	Northline Road	Approaches	Wearing surface	Routine	Erosion control	1
			Embankments & Streams	Embankments	Routine	Erosion control	1
G-039	Concession 4, Lot 13, Baptist Church Road Bridge	Baptist Church Road	Barriers	Railing systems	Structural	Barrier/railing system repair	1
G-040	Concession 4, Lot 12 & 13, Burkes Bridge	Concession 4	Barriers	Hand railings	Structural	Hand rail repairs	2
			Beams/Main Longitudinal Elements	Floor beams (steel)	Structural	Structural steel repair	2
			Barriers	Railing systems	Structural	Barrier/railing system repair	2
			Joints	Seals (open)	Structural	Bridge Joint Repair	2
G-041	Concession 4, Burkes Overflow Bridge	Concession 4	Barriers	Railing systems	Structural	Barrier/railing system repair	1
G-043	Glenelg Centre Bridge, Concession 5, Lot 17	Concession Rd 4	Joints	Seals (strip)	Routine	Bridge cleaning	1
G-044	Concession 2-3N, Lot 32	N Line	Accessories	Signs	Routine	Sign Repair	1
G-046	Concession 2 & 3N, Lot 43, McQuarrie Bridge	NorthLine	Barriers	Railing systems	Structural	Barrier/railing system repair	1
			Barriers	Railing systems	Structural	Barrier/railing system repair	1


2024 Maintenance Needs



Site #	Structure Name	Road Name	Element Name	Element Group	Needs Type	Maintenance Needs	Time Period (yrs)
N-052	Concession 2/3, Lot 5	Concession Rd 2 WGR	Signs	Signs	Structural	Sign Repair	1
N-055	Hampden Bridge, Concession 17, Lot 20/21	Side Rd 20	Decks	Wearing surface	Structural	Asphalt Repairs	2
			Approaches	Wearing surface	Structural	Asphalt Repairs	2
N-056	Concession 15/16, Lot 27	Concession Rd 16	Beams/Main Longitudinal Elements	Verticals/diagonals	Structural	Structural steel repair	2
N-059	Concession 11/12, Lot 30	Concession Rd 12	Barriers	Railing system	Structural	Barrier/railing system repair	1
			Approaches	Railing system	Routine	Barrier/railing system repair	1
N-065	Riest Bridge, Concession 5/6, Lot 9	Concession Rd 6	Approaches	Wearing surface	Structural	Asphalt Repairs	2
			Approaches	Curbs	Routine	Bridge cleaning	2
N-067	Concession 2/3, Lot 63	Concession Rd 2 WGR	Embankments & Streams	Embankments	Routine	Erosion control	1
			Signs	Signs	Routine	Sign Repair	1
			Approaches	Railing systems	Structural	Barrier/railing system repair	1
N-068	Concession 3, Lot 63/64	63 Rd	Barriers	Railing system	Structural	Barrier/railing system repair	2
N-163	Letter Breen Rd. Culvert, Letter Breen Road, Conc. 2, Lot 55/56	Letterbreen Rd	Culverts	Outlet Components	Routine	Remove vegetation	2
N-188	Sideroad 25, Conc. 12, Lot 25/26	Side Rd 25	Embankments & Streams	Embankments	Routine	Erosion control	1

APPENDIX D

CHANGE IN EMERGENCY RESPONSE TIME MAPS



Structure: B-002


Travel Time Difference: 1.6 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-002 - Durham	11.2	14.1	N/W Barrier
B-002 - Durham	11.2	14.1	Original
B-002 - Hanover	12.8	12.2	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-004

Travel Time Difference: 0.3 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-004 - Durham	14.8	17.9	N/W Barrier
B-004 - Chelsey	14.5	17.3	Original
B-004 - Chelsey	14.5	17.3	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-005


Travel Time Difference: 2.6 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-005 - Durham	13.7	17.1	N/W Barrier
B-005 - Durham	13.7	17.1	Original
B-005 - Chelsey	16.3	18.5	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-007


Travel Time Difference: 0.7 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-007 - Durham	21.5	20	N/W Barrier
B-007 - Durham	21.5	20	Original
B-007 - Chelsey	22.2	20.8	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-010


Travel Time Difference: 1.7 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-010 - Durham	12.7	14	N/W Barrier
B-010 - Durham	12.7	14	Original
B-010 - Durham	14.4	15.9	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-012


Travel Time Difference: 4.4 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-012 - Durham	11.3	13.1	N/W Barrier
B-012 - Durham	11.3	13.1	Original
B-012 - Durham	15.8	16.9	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-013


Travel Time Difference: 3.4 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-013 - Durham	9.4	10.5	N/W Barrier
B-013 - Durham	9.4	10.5	Original
B-013 - Durham	12.8	12.4	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-014


Travel Time Difference: 1.5 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-014 - Durham	10.2	12.7	N/W Barrier
B-014 - Durham	10.2	12.7	Original
B-014 - Durham	11.7	13.1	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-015


Travel Time Difference: 2.2 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-015 - Durham	9	11.1	N/W Barrier
B-015 - Durham	9	11.1	Original
B-015 - Durham	11.1	11.1	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-016


Travel Time Difference: 2.2 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-016 - Durham	8.9	11	N/W Barrier
B-016 - Durham	8.9	11	Original
B-016 - Durham	11	10.9	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-017


Travel Time Difference: 0.3 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-017 - Durham	9.7	9.7	N/W Barrier
B-017 - Durham	9.7	9.7	Original
B-017 - Durham	10	12	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-018


Travel Time Difference: 4.1 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-018 - Durham	5.8	6	N/W Barrier
B-018 - Durham	5.8	6	Original
B-018 - Durham	10	11	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17



Structure: B-019


Travel Time Difference: 0.9 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-019 - Durham	10.9	12	N/W Barrier
B-019 - Durham	10.9	12	Original
B-019 - Hanover	11.8	10.2	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-021


Travel Time Difference: 2.9 minutes

- Structure
-  Hospital
- █ Original (Fastest)
- █ N/W Barrier
- █ S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-021 - Durham	9.9	11.3	N/W Barrier
B-021 - Durham	9.9	11.3	Original
B-021 - Hanover	12.8	10.9	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-022

Travel Time Difference: 1.5 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-022 - Durham	10.2	11.6	N/W Barrier
B-022 - Durham	10.2	11.6	Original
B-022 - Durham	11.7	14.2	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-023


Travel Time Difference: 2.9 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-023 - Durham	11.3	12	N/W Barrier
B-023 - Durham	8.4	9.6	Original
B-023 - Durham	8.4	9.6	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-026


Travel Time Difference: 2.3 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-026 - Durham	9.4	9.5	N/W Barrier
B-026 - Durham	7.2	8.1	Original
B-026 - Durham	7.2	8.1	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-027


Travel Time Difference: 2.1 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-027 - Durham	7.3	7.4	N/W Barrier
B-027 - Durham	7.3	7.4	Original
B-027 - Durham	9.4	10.2	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-028


Travel Time Difference: 5.3 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-028 - Durham	3.8	3.6	N/W Barrier
B-028 - Durham	3.8	3.6	Original
B-028 - Durham	9.1	9.6	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17



Structure: B-104


Travel Time Difference: 4.1 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-104 - Durham	7.7	7.7	N/W Barrier
B-104 - Durham	7.7	7.7	Original
B-104 - Durham	11.8	14	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-105


Travel Time Difference: 1.4 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-105 - Durham	9.1	9.1	N/W Barrier
B-105 - Durham	9.1	9.1	Original
B-105 - Durham	10.5	12.6	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-107


Travel Time Difference: 2.1 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-107 - Hanover	10.2	8.4	N/W Barrier
B-107 - Hanover	8.1	6.3	Original
B-107 - Hanover	8.1	6.3	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17



Structure: B-112


Travel Time Difference: 0.3 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-112 - Durham	16	17.5	N/W Barrier
B-112 - Chelsey	15.7	18.9	Original
B-112 - Chelsey	15.7	18.9	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-113


Travel Time Difference: 0.7 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-113 - Durham	15.6	17.2	N/W Barrier
B-113 - Durham	15.6	17.2	Original
B-113 - Chelsey	16.3	19.2	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-114


Not a through road. Closure of B-114 would require full road closure north of structure

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-114 - Durham	9.4	10.8	N/W Barrier
B-114 - Durham	9.4	10.8	Original



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-115


Travel Time Difference: 2 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-115 - Hanover	9.6	8	N/W Barrier
B-115 - Hanover	9.6	8	Original
B-115 - Hanover	11.6	10.8	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: B-118


Travel Time Difference: 1.8 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-118 - Chelsey	10.4	11.7	N/W Barrier
B-118 - Chelsey	8.7	8.7	Original
B-118 - Chelsey	8.7	8.7	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-119


Travel Time Difference: 1.2 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-119 - Chelsey	7.3	7.3	N/W Barrier
B-119 - Chelsey	6.2	6	Original
B-119 - Chelsey	6.2	6	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17



Structure: B-120


Travel Time Difference: 3 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-120 - Chelsey	11.9	12.4	N/W Barrier
B-120 - Chelsey	8.9	8.9	Original
B-120 - Chelsey	8.9	8.9	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-121


Travel Time Difference: 0.4 minutes

- Structure
- Hospital
- █ Original (Fastest)
- █ N/W Barrier
- █ S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-121 - Chelsey	8.5	9.2	N/W Barrier
B-121 - Chelsey	8.2	8.1	Original
B-121 - Chelsey	8.2	8.1	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-195


Travel Time Difference: 1.9 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-195 - Durham	10.8	10.7	N/W Barrier
B-195 - Durham	8.9	11	Original
B-195 - Durham	8.9	11	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17



Structure: B-198


Travel Time Difference: 4.5 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
B-198 - Durham	12.4	14.5	N/W Barrier
B-198 - Durham	12.4	14.5	Original
B-198 - Durham	16.9	18.6	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: D-001

Travel Time Difference: 1 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
D-001 - Durham	4	2.1	N/W Barrier
D-001 - Durham	3	1.6	Original
D-001 - Durham	3	1.6	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: D-101


Travel Time Difference: 0.7 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
D-101 - Durham	2.8	1.4	N/W Barrier
D-101 - Durham	2.1	1.1	Original
D-101 - Durham	2.1	1.1	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17



Structure: G-030


Travel Time Difference: 0.9 minutes

- Structure
-  Hospital
- █ Original (Fastest)
- █ N/W Barrier
- █ S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-030 - Durham	15.4	17.9	N/W Barrier
G-030 - Durham	15.4	17.9	Original
G-030 - Durham	16.2	19.2	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: G-031


Travel Time Difference: 0.9 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-031 - Durham	10.3	11.2	N/W Barrier
G-031 - Durham	10.3	11.2	Original
G-031 - Durham	11.2	11.2	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: G-032


Travel Time Difference: 0.1 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-032 - Markdale	13.5	13.9	N/W Barrier
G-032 - Markdale	13.5	13.9	Original
G-032 - Markdale	13.5	13.9	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: G-035


Travel Time Difference: 3.6 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-035 - Markdale	3.7	2.8	N/W Barrier
G-035 - Markdale	3.7	2.8	Original
G-035 - Markdale	7.3	6.8	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: G-039


Travel Time Difference: 0.7 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-039 - Durham	12.1	13.3	N/W Barrier
G-039 - Durham	12.1	13.3	Original
G-039 - Durham	12.8	14.2	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17



Structure: G-043

Travel Time Difference: 1.5 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-043 - Markdale	13.3	13.3	N/W Barrier
G-043 - Markdale	13.3	13.3	Original
G-043 - Durham	14.7	16.3	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17



Structure: G-045


Travel Time Difference: 5 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-045 - Markdale	18.4	15.2	N/W Barrier
G-045 - Durham	13.4	14.5	Original
G-045 - Durham	13.4	14.5	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17



Structure: G-046


Travel Time Difference: 0.8 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-046 - Markdale	15.2	15.4	N/W Barrier
G-046 - Markdale	15.2	15.4	Original
G-046 - Durham	15.9	16.5	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17



Structure: G-047


Travel Time Difference: 2.5 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-047 - Markdale	14.3	14.8	N/W Barrier
G-047 - Markdale	14.3	14.8	Original
G-047 - Durham	16.8	17.1	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: G-048


Travel Time Difference: 1 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-048 - Durham	11.9	13	N/W Barrier
G-048 - Durham	11.9	13	Original
G-048 - Durham	13	14.4	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: G-126


Travel Time Difference: 2.2 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-126 - Markdale	13.9	15.2	N/W Barrier
G-126 - Markdale	11.7	12.1	Original
G-126 - Markdale	11.7	12.1	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17



Structure: G-148


Travel Time Difference: 1.7 minutes

- Structure
-  Hospital
- █ Original (Fastest)
- █ N/W Barrier
- █ S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-148 - Markdale	11.9	13.1	N/W Barrier
G-148 - Markdale	11.9	13.1	Original
G-148 - Markdale	13.6	14.2	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: G-154


Travel Time Difference: 3.9 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-154 - Markdale	9.5	10.2	N/W Barrier
G-154 - Markdale	9.5	10.2	Original
G-154 - Markdale	13.3	13	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: G-197


Travel Time Difference: 4.1 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
G-197 - Markdale	11.4	11.9	N/W Barrier
G-197 - Markdale	11.4	11.9	Original
G-197 - Markdale	15.5	15.9	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17



Structure: N-050


Travel Time Difference: 1.9 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-050 - Hanover	4.7	4.3	N/W Barrier
N-050 - Hanover	4.7	4.3	Original
N-050 - Hanover	6.6	7	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-052


Travel Time Difference: 2.3 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-052 - Durham	9.8	9	N/W Barrier
N-052 - Durham	7.4	7.7	Original
N-052 - Durham	7.4	7.7	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-053


Travel Time Difference: 1.6 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-053 - Hanover	6.6	6.8	N/W Barrier
N-053 - Hanover	6.6	6.8	Original
N-053 - Hanover	8.2	9	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-054


Travel Time Difference: 5.6 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-054 - Hanover	12.9	15.1	N/W Barrier
N-054 - Hanover	7.3	7.9	Original
N-054 - Hanover	7.3	7.9	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-055


Travel Time Difference: 1.9 minutes

- Structure
-  Hospital
- █ Original (Fastest)
- █ N/W Barrier
- █ S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-055 - Hanover	13.5	14.8	N/W Barrier
N-055 - Hanover	11.6	12.5	Original
N-055 - Hanover	11.6	12.5	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-056


Travel Time Difference: 0.8 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-056 - Durham	15.3	14.3	N/W Barrier
N-056 - Hanover	14.6	16.6	Original
N-056 - Hanover	14.6	16.6	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-057


Travel Time Difference: 3.7 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-057 - Hanover	16.2	18.3	N/W Barrier
N-057 - Hanover	12.6	12.7	Original
N-057 - Hanover	12.6	12.7	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-059


Travel Time Difference: 2.4 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-059 - Durham	15.7	16.3	N/W Barrier
N-059 - Durham	15.7	16.3	Original
N-059 - Hanover	18.1	21.9	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17



Structure: N-062


Travel Time Difference: 1.2 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-062 - Durham	15.7	14.8	N/W Barrier
N-062 - Durham	15.7	14.8	Original
N-062 - Hanover	16.9	19.7	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-063


Travel Time Difference: 0.8 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-063 - Hanover	15.9	17.2	N/W Barrier
N-063 - Hanover	15.1	16.2	Original
N-063 - Hanover	15.1	16.2	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-064


Travel Time Difference: 2.7 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-064 - Hanover	18.4	20.5	N/W Barrier
N-064 - Hanover	15.8	17	Original
N-064 - Hanover	15.8	17	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-065


Travel Time Difference: 1 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-065 - Mount Forest	19.4	22.9	N/W Barrier
N-065 - Hanover	18.4	20.5	Original
N-065 - Hanover	18.4	20.5	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17



Structure: N-066


Travel Time Difference: 2.6 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-066 - Mount Forest	16.2	18.5	N/W Barrier
N-066 - Mount Forest	16.2	18.5	Original
N-066 - Mount Forest	18.8	22.2	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-067


Travel Time Difference: 4.8 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-067 - Mount Forest	8.9	9.4	N/W Barrier
N-067 - Mount Forest	8.9	9.4	Original
N-067 - Mount Forest	13.7	15.8	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-068


Travel Time Difference: 2 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-068 - Mount Forest	9	9.5	N/W Barrier
N-068 - Mount Forest	9	9.5	Original
N-068 - Mount Forest	11	12.5	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-069


Travel Time Difference: 2.5 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-069 - Mount Forest	6.8	7.2	N/W Barrier
N-069 - Mount Forest	6.8	7.2	Original
N-069 - Mount Forest	9.3	10.6	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-071


Travel Time Difference: 2.2 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-071 - Mount Forest	7	7.4	N/W Barrier
N-071 - Mount Forest	7	7.4	Original
N-071 - Mount Forest	9.1	10.4	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-072


Travel Time Difference: 2.8 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-072 - Durham	7.1	6	N/W Barrier
N-072 - Durham	7.1	6	Original
N-072 - Durham	9.9	10.6	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-163


Travel Time Difference: 4.7 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-163 - Mount Forest	8.5	8	N/W Barrier
N-163 - Mount Forest	8.5	8	Original
N-163 - Mount Forest	13.2	15.8	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-165


Travel Time Difference: 1 minutes

- Structure
- Hospital
- █ Original (Fastest)
- █ N/W Barrier
- █ S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-165 - Durham	6.5	5.1	N/W Barrier
N-165 - Durham	6.5	5.1	Original
N-165 - Durham	7.5	7.7	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-171

Travel Time Difference: 3.9 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-171 - Hanover	17.6	19.7	N/W Barrier
N-171 - Hanover	13.8	15.8	Original
N-171 - Hanover	13.8	15.8	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17



Structure: N-172


Travel Time Difference: 0.9 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-172 - Durham	16.6	15.8	N/W Barrier
N-172 - Hanover	15.7	18.3	Original
N-172 - Hanover	15.7	18.3	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-178


Travel Time Difference: 2.4 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-178 - Hanover	16.6	19.3	N/W Barrier
N-178 - Hanover	14.1	16.1	Original
N-178 - Hanover	14.1	16.1	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17




Structure: N-179


Travel Time Difference: 1.9 minutes

- Structure
- Hospital
- █ Original (Fastest)
- █ N/W Barrier
- █ S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-179 - Hanover	14.9	16.9	N/W Barrier
N-179 - Hanover	13	14.4	Original
N-179 - Hanover	13	14.4	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-183


Travel Time Difference: 1.1 minutes

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-183 - Mount Forest	18.3	21.9	N/W Barrier
N-183 - Mount Forest	18.3	21.9	Original
N-183 - Hanover	19.4	21.5	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-187


Travel Time Difference: 0.8 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-187 - Mount Forest	17	19.1	N/W Barrier
N-187 - Mount Forest	17	19.1	Original
N-187 - Hanover	17.8	21	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: N-190


Travel Time Difference: 0.4 minutes

- Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-190 - Hanover	16.2	17.9	N/W Barrier
N-190 - Hanover	15.8	17.9	Original
N-190 - Hanover	15.8	17.9	S/E Barrier



Created by: Grey County GIS
Date: October 17, 2024
NAD83 UTM Zone 17



Structure: N-199


Travel Time Difference: 0.6 minutes

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
N-199 - Durham	17.4	18	N/W Barrier
N-199 - Hanover	16.8	20.2	Original
N-199 - Hanover	16.8	20.2	S/E Barrier




Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: P-101

- Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
P-101 - Durham	2.7	1.3	N/W Barrier
P-101 - Durham	2.7	1.3	Original
P-101 - Durham	2.7	1.3	S/E Barrier




Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: P-102

- Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Nearest Hospital	Travel Time (min)	Kilometers	Scenario
P-102 - Hanover	9.9	8.8	N/W Barrier
P-102 - Hanover	9.9	8.8	Original
P-102 - Hanover	9.9	8.8	S/E Barrier



Created by: Grey County GIS
 Date: October 17, 2024
 NAD83 UTM Zone 17




Structure: B-001


Travel Time Difference: 2.9 minutes

- Prioritized Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
B-001 - Chelsey	6.9	7.3	Original
B-001 - Chelsey	6.9	7.3	S/E Barrier
B-001 - Chelsey	9.8	10.1	N/W Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17




Structure: B-006


Travel Time Difference: 2.1 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
B-006 - Durham	13.8	17.2	Original
B-006 - Durham	13.8	17.2	N/W Barrier
B-006 - Chelsey	16.0	18.1	S/E Barrier



Created by: Grey County GIS
 Date: Sept 5, 2024
 NAD83 UTM Zone 17




Structure: B-008


Travel Time Difference: 1.3 minutes

- Prioritized Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
B-008 - Durham	15.6	17.1	Original
B-008 - Chelsey	16.9	19.8	S/E Barrier
B-008 - Durham	15.6	17.1	N/W Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: B-009


Travel Time Difference: 3.4 minutes

- Prioritized Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
B-009 - Durham	14.6	16.1	Original
B-009 - Durham	14.6	16.1	N/W Barrier
B-009 - Durham	17.9	21.3	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: B-011


Travel Time Difference: 5.4 minutes

- Prioritized Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
B-011 - Durham	11.9	14.1	Original
B-011 - Durham	11.9	14.1	N/W Barrier
B-011 - Durham	17.4	19.0	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: B-020


Travel Time Difference: 2.4 minutes

- Prioritized Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
B-020 - Durham	10.1	11.5	Original
B-020 - Durham	10.1	11.5	N/W Barrier
B-020 - Hanover	12.6	10.7	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: B-025


Travel Time Difference: 0.2 minutes

- Prioritized Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
B-025 - Hanover	7.5	6.8	Original
B-025 - Hanover	7.5	6.8	N/W Barrier
B-025 - Hanover	7.7	7.0	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17




Structure: G-033


Travel Time Difference: 2.6 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
G-033 - Markdale	12.0	11.6	Original
G-033 - Markdale	14.6	12.7	N/W Barrier
G-033 - Markdale	12.0	11.6	S/E Barrier



Created by: Grey County GIS
 Date: Sept 5, 2024
 NAD83 UTM Zone 17



Structure: G-037


Travel Time Difference: 1.8 minutes

- Prioritized Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
G-037 - Durham	10.0	8.3	Original
G-037 - Durham	11.8	10.7	N/W Barrier
G-037 - Durham	10.0	8.3	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: G-038


Travel Time Difference: 1.7 minutes

- Prioritized Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
G-038 - Durham	10.0	8.4	Original
G-038 - Durham	11.7	10.6	N/W Barrier
G-038 - Durham	10.0	8.4	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: G-040


Travel Time Difference: 1.7 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
G-040 - Durham	13.7	14.8	Original
G-040 - Durham	15.4	16.9	N/W Barrier
G-040 - Durham	13.7	14.8	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: G-041

Travel Time Difference: 1.6 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
G-041 - Durham	13.7	14.9	Original
G-041 - Durham	15.3	16.8	N/W Barrier
G-041 - Durham	13.7	14.9	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17




Structure: G-044


Travel Time Difference: 5.2 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
G-044 - Durham	13.0	14.1	Original
G-044 - Markdale	18.1	17.8	N/W Barrier
G-044 - Durham	13.0	14.1	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17




Structure: G-132


Travel Time Difference: Baseline not a through road. Closure of G-132 would require full road closure north of structure

- Prioritized Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
G-132 - Durham	7.2	6.0	Original
G-132 - Durham	7.2	6.0	N/W Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: G-133


Travel Time Difference: 1.1 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
G-133 - Durham	6.3	4.3	Original
G-133 - Durham	7.4	6.2	N/W Barrier
G-133 - Durham	6.3	4.3	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: N-051


Travel Time Difference: 3.7 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
N-051 - Hanover	8.7	9.4	Original
N-051 - Durham	12.5	15.1	N/W Barrier
N-051 - Hanover	8.7	9.4	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: N-058


Travel Time Difference: 2.5 minutes

- Prioritized Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
N-058 - Durham	15.9	16.5	Original
N-058 - Durham	15.9	16.5	N/W Barrier
N-058 - Hanover	18.4	21.5	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: N-060


Travel Time Difference: 3.2 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
N-060 - Durham	15.5	16.1	Original
N-060 - Durham	15.5	16.1	N/W Barrier
N-060 - Hanover	18.7	21.9	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17




Structure: N-061


Travel Time Difference: 1.4 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
N-061 - Durham	15.7	14.6	Original
N-061 - Durham	15.7	14.6	N/W Barrier
N-061 - Hanover	17.1	19.3	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: N-070


Travel Time Difference: 4.8 minutes

- Prioritized Structure
-  Hospital
-  Original (Fastest)
-  N/W Barrier
-  S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
N-070 - Mount Forest	5.7	5.3	Original
N-070 - Mount Forest	5.7	5.3	N/W Barrier
N-070 - Mount Forest	10.4	7.7	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17




Structure: N-184


Travel Time Difference: 2.7 minutes

- Prioritized Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
N-184 - Mount Forest	15.3	18.4	Original
N-184 - Mount Forest	15.3	18.4	N/W Barrier
N-184 - Mount Forest	18.0	20.1	S/E Barrier



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: N-185


Travel Time Difference: 2.4 minutes

- Prioritized Structure
-  Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
N-185 - Mount Forest	15.5	18.5	N/W Barrier
N-185 - Mount Forest	17.9	19.9	S/E Barrier
N-185 - Mount Forest	15.5	18.5	Original



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17



Structure: N-188


Travel Time Difference: 1.4 minutes

- Prioritized Structure
- Hospital
- Original (Fastest)
- N/W Barrier
- S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
N-188 - Hanover	18.4	20.6	N/W Barrier
N-188 - Hanover	17.1	18.9	S/E Barrier
N-188 - Hanover	17.1	18.9	Original



Created by: Grey County GIS
 Date: Sept 5, 2024
 NAD83 UTM Zone 17




Structure: N-189

Travel Time Difference: 2.9 minutes


- Prioritized Structure
- Hospital
- █ Original (Fastest)
- █ N/W Barrier
- █ S/E Barrier

Name - Closest Hospital	Travel Time (min)	Kilometers	Scenario
N-189 - Hanover	19.2	21.3	N/W Barrier
N-189 - Hanover	16.3	18.2	S/E Barrier
N-189 - Hanover	16.3	18.2	Original



Created by: Grey County GIS
Date: Sept 5, 2024
NAD83 UTM Zone 17

APPENDIX E
STRUCTURE DETOUR MAPS




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m

344250-344498 N Line
Priceville, ON N0C 1K0

- ↑ 1. Head west on N Line toward Glenelg Rd 23/County Rd 23
_____ 300 m
- ↪ 2. Turn right at the 1st cross street onto Glenelg Rd 23/County Rd 23
_____ 2.0 km
- ↪ 3. Turn right at the 1st cross street onto Concession Rd 4
_____ 2.1 km
- ↪ 4. Turn right onto Side Rd 40
_____ 2.1 km
- ↪ 5. Turn right onto N Line
_____ 1.7 km

344250-344498 N Line
Priceville, ON N0C 1K0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m


172309-172399 Side Rd 25

West Grey, ON N0G 2M0

- ↑ 1. Head south on Side Rd 25 toward Concession Rd 12
_____ 1.9 km
- ↘ 2. Turn right at the 1st cross street onto Concession Rd 12
_____ 2.0 km
- ↘ 3. Turn right onto Side Rd 20
_____ 2.0 km
- ↘ 4. Turn right onto Concession Rd 14
_____ 2.2 km
- ↘ 5. Turn right onto Side Rd 25
_____ 350 m

172309-172399 Side Rd 25

West Grey, ON N0G 2M0




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m

171601-171899 Side Rd 25
Ayton, ON N0G 1C0

- ↑ 1. Head north on Side Rd 25 toward Grey County Rd 9
_____ 1.7 km
 - ↘ 2. Turn right at the 1st cross street onto Grey County Rd 9
_____ 3.7 km
 - ↘ 3. Turn right onto Baseline Rd
_____ 550 m
 - ↘ 4. Turn right onto Concession Rd 8
_____ 2.3 km
 - ↘ 5. Turn right onto Side Rd 25
_____ 260 m
- i** Destination will be on the right

West Grey
Ontario




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m

Traverston

Ontario N0C 1H0

- ↑ 1. Head north on Traverston Rd toward Grey Rd 12
_____ 2.0 km
- ↘ 2. Turn right onto Grey Rd 12
_____ 2.0 km
- ↘ 3. Turn right onto Glenelg Rd 23/County Rd 23
_____ 2.0 km
- ↘ 4. Turn right onto Concession Rd 8
_____ 2.6 km
- ↘ 5. Turn right onto Traverston Rd
⚠ Parts of this road may be closed at certain times or days
_____ 550 m

494551-494555 Traverston Rd
Markdale, ON N0C 1H0




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m

344250-344498 N Line
Priceville, ON N0C 1K0

- ↑ 1. Head west on N Line toward Glenelg Rd 23/County Rd 23
_____ 300 m
- ↪ 2. Turn right at the 1st cross street onto Glenelg Rd 23/County Rd 23
_____ 2.0 km
- ↪ 3. Turn right at the 1st cross street onto Concession Rd 4
_____ 2.1 km
- ↪ 4. Turn right onto Side Rd 40
_____ 2.1 km
- ↪ 5. Turn right onto N Line
_____ 1.7 km

344250-344498 N Line
Priceville, ON N0C 1K0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 1 km



Use caution—bicycling directions may not always reflect real-world conditions


343250-343748 N Line

Priceville, ON N0C 1K0

- ↑ 1. Head west on N Line toward Concession 2
_____ 2.9 km
- ↪ 2. Turn right onto Concession 2
_____ 2.4 km
- ↪ 3. Turn right onto Concession Rd 4
_____ 5.7 km
- ↪ 4. Turn right onto Baptist Church Rd
_____ 2.0 km
- ↪ 5. Turn right onto N Line
_____ 2.9 km

343250-343748 N Line

Priceville, ON N0C 1K0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m



Use caution—bicycling directions may not always reflect real-world conditions


343250-343748 N Line

Priceville, ON N0C 1K0

- ↑ 1. Head east on N Line toward Camp Oliver Rd
_____ 750 m
- ↪ 2. Turn right onto Camp Oliver Rd
_____ 2.1 km
- ↪ 3. Turn right onto Grey County Rd 4
_____ 3.7 km
- ↪ 4. Turn right onto Concession 2
_____ 2.2 km
- ↪ 5. Turn right onto N Line
_____ 2.9 km

343250-343748 N Line

Priceville, ON N0C 1K0




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m

341761 Concession Rd 2 NDR
Hanover, ON N4N 3B8

- ↑ 1. Head east on Concession Rd 2 NDR toward Allan Park Rd
_____ 700 m
- ↘ 2. Turn right at the 1st cross street onto Allan Park Rd
_____ 2.0 km
- ↘ 3. Turn right onto Grey County Rd 4
_____ 2.3 km
- ⤷ 4. At the roundabout, take the 1st exit onto Grey Road 3/County Rd 3
⚠️ Parts of this road may be closed at certain times or days
_____ 2.8 km
- ↘ 5. Turn right onto Concession Rd 2 NDR
_____ 1.3 km

Concession Rd 2 NDR
Hanover, ON N4N 3B8




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m

341791-341761 Concession Rd 2 NDR
Hanover, ON N4N 3B8

- ↑ 1. Head east on Concession Rd 2 NDR toward Allan Park Rd
_____ 600 m
- ↶ 2. Turn left at the 1st cross street onto Allan Park Rd
_____ 2.1 km
- ↶ 3. Turn left onto Concession 4 Ndr/Concession Rd 4
_____ 2.0 km
- ↶ 4. Turn left onto Grey Road 3/County Rd 3
_____ 2.1 km
- ↶ 5. Turn left onto Concession Rd 2 NDR
 - 📘 Destination will be on the left
_____ 1.2 km

Concession Rd 2 NDR
Hanover, ON N4N 3B8




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m

172308-172200 Side Rd 25
West Grey, ON N0G 2M0

- ↑ 1. Head west on Side Rd 25 toward Concession Rd 12
_____ 1.1 km
- ↪ 2. Turn right at the 1st cross street onto Concession Rd 12
_____ 2.0 km
- ↪ 3. Turn right onto Side Rd 20
_____ 2.0 km
- ↪ 4. Turn right onto Concession Rd 14
_____ 2.2 km
- ↪ 5. Turn right onto Side Rd 25
_____ 1.1 km

172308-172200 Side Rd 25
West Grey, ON N0G 2M0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m


421831-421623 Concession 6 NDR

West Grey, ON NOG 1S0

- ↑ 1. Head west on Concession 6 NDR/Concession Rd 6 toward Grey Road 3/County Rd 3
_____ 1.0 km
- ↶ 2. Turn left at the 1st cross street onto Grey Road 3/County Rd 3
_____ 2.0 km
- ↶ 3. Turn left onto Concession 4 Ndr/Concession Rd 4
_____ 2.0 km
- ↶ 4. Turn left onto Allan Park Rd
_____ 2.0 km
- ↶ 5. Turn left onto Concession 6 NDR/Concession Rd 6
_____ 1.0 km

421624-421832 Concession 6 NDR

West Grey, ON NOG 1S0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 1 km



Use caution—bicycling directions may not always reflect real-world conditions


343250-343748 N Line

Priceville, ON N0C 1K0

- ↑ 1. Head west on N Line toward Concession 2
_____ 2.9 km
- ↪ 2. Turn right onto Concession 2
_____ 2.4 km
- ↪ 3. Turn right onto Concession Rd 4
_____ 5.7 km
- ↪ 4. Turn right onto Baptist Church Rd
_____ 2.0 km
- ↪ 5. Turn right onto N Line
_____ 2.9 km

343250-343748 N Line

Priceville, ON N0C 1K0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m



Use caution—bicycling directions may not always reflect real-world conditions


343250-343748 N Line

Priceville, ON N0C 1K0

- ↑ 1. Head east on N Line toward Camp Oliver Rd
_____ 750 m
- ↪ 2. Turn right onto Camp Oliver Rd
_____ 2.1 km
- ↪ 3. Turn right onto Grey County Rd 4
_____ 3.7 km
- ↪ 4. Turn right onto Concession 2
_____ 2.2 km
- ↪ 5. Turn right onto N Line
_____ 2.9 km

343250-343748 N Line

Priceville, ON N0C 1K0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 1 km



Use caution—bicycling directions may not always reflect real-world conditions


261596 Concession Rd 18

Neustadt, ON N0G 2M0

- ↑ 1. Head west on Concession Rd 18 toward Grey Rd 28/County Rd 28
_____ 5.3 km
- ↶ 2. Turn left onto Grey Rd 10
_____ 2.0 km
- ↶ 3. Turn left onto Concession Rd 16
_____ 5.3 km
- ↶ 4. Turn left onto Grey Road 3/County Rd 3
_____ 2.0 km
- ↶ 5. Turn left onto Concession Rd 18
_____ 88 m

261596 Concession Rd 18

Neustadt, ON N0G 2M0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 1 km



Use caution—bicycling directions may not always reflect real-world conditions


261596 Concession Rd 18

Neustadt, ON N0G 2M0

- ↑ 1. Head east on Concession Rd 18 toward Grey Road 3/County Rd 3
76 m
- ↶ 2. Turn left onto Grey Road 3/County Rd 3
1.3 km
- ↶ 3. Turn left onto Normanby Bentinck Townline
4.1 km
- ↶ 4. Turn left onto Grey Rd 28/County Rd 28
1.3 km
- ↶ 5. Turn left onto Concession Rd 18
3.9 km

261596 Concession Rd 18

Neustadt, ON N0G 2M0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m


303349-303101 S Line

West Grey, ON N0G 1R0

- ↑ 1. Head west on S Line toward Concession Rd 1
_____ 750 m
- ↗ 2. S Line turns slightly right and becomes Concession Rd 1
_____ 1.2 km
- ↘ 3. Turn right onto Grey County Rd 4
_____ 1.6 km
- ↘ 4. Turn right onto Concession Rd 2
_____ 1.5 km
- ↘ 5. Turn right onto S Line
_____ 750 m

303349-303101 S Line

West Grey, ON N0G 1R0




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m

73001-73199 Side Rd 10
Neustadt, ON N0G 2M0

- ↑ 1. Head north on 10th Sideroad Sdr/Side Rd 10 toward Concession Rd 2 SDR/Concession Rd 2
_____ 1.1 km
- ↶ 2. Turn left onto Concession Rd 2 SDR/Concession Rd 2
_____ 2.0 km
- ↶ 3. Turn left onto Grey Rd 28/County Rd 28
_____ 1.1 km
- ↶ 4. Turn left onto Normanby Bentinck Townline
_____ 2.2 km
- ↶ 5. Turn left onto 10th Sideroad Sdr/Side Rd 10
_____ 120 m

73198-73000 Side Rd 10
Neustadt, ON N0G 2M0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m


West Grey

Ontario

- ↑ 1. Head west on Welbeck Rd toward Baseline
_____ 600 m
- ↪ 2. Turn right onto Baseline
_____ 1.8 km
- ↪ 3. Turn right onto 3rd SIDEROAD WGR/Side Rd 3
_____ 1.6 km
- ↪ 4. Turn right at the 1st cross street onto Concession Rd 2 WGR
_____ 1.6 km
- ↪ 5. Turn right to stay on Concession Rd 2 WGR
_____ 400 m
- ↪ 6. Turn right onto Welbeck Rd
_____ 850 m

West Grey

Ontario



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m


West Grey

Ontario

- ↑ 1. Head north on Baseline toward Concession Rd 12
_____ 1.4 km
- ↪ 2. Turn right onto 3rd SIDEROAD WGR/Side Rd 3
_____ 1.6 km
- ↪ 3. Turn right at the 1st cross street onto Concession Rd 2 WGR
_____ 1.6 km
- ↪ 4. Turn right to stay on Concession Rd 2 WGR
_____ 400 m
- ↪ 5. Turn right onto Welbeck Rd
_____ 1.5 km
- ↪ 6. Turn right onto Baseline
_____ 400 m

West Grey

Ontario




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m

Concession Rd 12
Elmwood, ON N0G 1S0

- ↑ 1. Head east on Concession Rd 12 toward 5th Sideroad Ndr/Side Rd 5
_____ 1.4 km
- ↶ 2. Turn left at the 1st cross street onto 5th Sideroad Ndr/Side Rd 5
_____ 2.0 km
- ↶ 3. Turn left onto Concession 14 Ndr/Concession Rd 14
_____ 2.0 km
- ↶ 4. Turn left onto Bruce Rd 10
_____ 2.0 km
- ↶ 5. Turn left onto Concession Rd 12
_____ 550 m

Concession Rd 12
Elmwood, ON N0G 1S0



Imagery ©2024 CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m


Concession Rd 2 WGR

Mount Forest, ON N0G 2L0

- ↑ 1. Head northwest on Concession Rd 2 WGR toward Rd 71
 ⚠️ Parts of this road may be closed at certain times or days
 _____ 1.1 km
- ↪️ 2. Turn right onto Rd 71
 _____ 2.2 km
- ↪️ 3. Turn right onto Grey Rd 6/County Rd 6
 _____ 1.3 km
- ↪️ 4. Turn right at the 1st cross street onto ON-89 W
 _____ 2.1 km
- ↪️ 5. Turn right onto Concession Rd 2 WGR
 ⚠️ Parts of this road may be closed at certain times or days
 _____ 180 m

Concession Rd 2 WGR

Mount Forest, ON N0G 2L0




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m

West Grey
Ontario N0G 1R0

- ↑ 1. Head west on 3rd SIDEROAD WGR/Side Rd 3 toward Concession Rd 2 WGR
_____ 2.5 km
- ↘ 2. Turn right onto Concession Rd 2 WGR
_____ 1.9 km
- ↘ 3. Turn right onto Grey Rd 25/County Rd 25
_____ 2.5 km
- ↘ 4. Turn right onto Hwy 6 S/ON-6 S
_____ 1.9 km
- ↘ 5. Turn right at the 1st cross street onto 3rd SIDEROAD WGR/Side Rd 3
_____ 97 m

West Grey
Ontario N0G 1R0




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m

522699-522571 Welbeck Rd
West Grey, ON N0G 1R0

- ↑ 1. Head west on Welbeck Rd toward Baseline
_____ 450 m
- ↘ 2. Turn right onto Baseline
_____ 1.8 km
- ↘ 3. Turn right onto 3rd SIDEROAD WGR/Side Rd 3
_____ 1.6 km
- ↘ 4. Turn right at the 1st cross street onto Concession Rd 2 WGR
_____ 1.6 km
- ↘ 5. Turn right to stay on Concession Rd 2 WGR
_____ 400 m
- ↘ 6. Turn right onto Welbeck Rd
 - 📘 Destination will be on the right
 _____ 900 m


522699-522571 Welbeck Rd
West Grey, ON N0G 1R0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 1 km

182401-182813 Concession Rd 12
West Grey, ON

- ↑ 1. Head east on Concession Rd 12 toward Concession Rd 2 WGR
_____ 1.9 km
- ↶ 2. Turn left at the 1st cross street onto Concession Rd 2 WGR
_____ 1.9 km
- ↶ 3. Turn left onto 21 Rd
_____ 1.6 km
- ↗ 4. 21 Rd turns slightly right and becomes Baseline Rd
_____ 190 m
- ↶ 5. Turn left onto Concession Rd 14
_____ 2.1 km
- ↶ 6. Turn left onto Side Rd 25
_____ 2.2 km
- ↶ 7. Turn left onto Concession Rd 12
_____ 2.0 km




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m

171601-171899 Side Rd 25
Ayton, ON N0G 1C0

- ↑ 1. Head north on Side Rd 25 toward Grey County Rd 9
_____ 1.7 km
- ↘ 2. Turn right at the 1st cross street onto Grey County Rd 9
_____ 3.7 km
- ↘ 3. Turn right onto Baseline Rd
_____ 550 m
- ↘ 4. Turn right onto Concession Rd 8
_____ 2.3 km
- ↘ 5. Turn right onto Side Rd 25
 - i Destination will be on the right
 _____ 260 m

West Grey
Ontario



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m

384092 Concession Rd 4

West Grey, ON N0C 1K0

- ↑ 1. Head west on Concession Rd 4 toward Baptist Church Rd
950 m
- ↘ 2. Turn right at the 1st cross street onto Baptist Church Rd
2.0 km
- ↘ 3. Turn right onto Concession Rd 6
2.0 km
- ↘ 4. Turn right onto Glenelg Rd 23/County Rd 23
2.1 km
- ↘ 5. Turn right onto Concession Rd 4
1.0 km



West Grey

Ontario



Add stop



Save



Nearby




Send to phone

384092 Concession Rd 4

West Grey, ON N0C 1K0

Quick facts



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m


384092 Concession Rd 4

West Grey, ON N0C 1K0

- ↑ 1. Head west on Concession Rd 4 toward Baptist Church Rd
_____ 1.0 km
- ↶ 2. Turn left at the 1st cross street onto Baptist Church Rd
_____ 2.0 km
- ↶ 3. Turn left onto N Line
_____ 2.0 km
- ↶ 4. Turn left onto Glenelg Rd 23/County Rd 23
_____ 2.0 km
- ↶ 5. Turn left at the 1st cross street onto Concession Rd 4
_____ 1.1 km

384092 Concession Rd 4

West Grey, ON N0C 1K0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m

384092 Concession Rd 4

West Grey, ON N0C 1K0

- ↑ 1. Head west on Concession Rd 4 toward Baptist Church Rd
950 m
- ↘ 2. Turn right at the 1st cross street onto Baptist Church Rd
2.0 km
- ↘ 3. Turn right onto Concession Rd 6
2.0 km
- ↘ 4. Turn right onto Glenelg Rd 23/County Rd 23
2.1 km
- ↘ 5. Turn right onto Concession Rd 4
1.0 km



West Grey

Ontario



Add stop



Save



Nearby




Send to phone

384092 Concession Rd 4

West Grey, ON N0C 1K0

Quick facts




Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 500 m

384092 Concession Rd 4
West Grey, ON N0C 1K0

- ↑ 1. Head west on Concession Rd 4 toward Baptist Church Rd
_____ 1.0 km
- ↶ 2. Turn left at the 1st cross street onto Baptist Church Rd
_____ 2.0 km
- ↶ 3. Turn left onto N Line
_____ 2.0 km
- ↶ 4. Turn left onto Glenelg Rd 23/County Rd 23
_____ 2.0 km
- ↶ 5. Turn left at the 1st cross street onto Concession Rd 4
_____ 1.1 km


384092 Concession Rd 4
West Grey, ON N0C 1K0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 1 km

182401-182813 Concession Rd 12
West Grey, ON

- ↑ 1. Head east on Concession Rd 12 toward Concession Rd 2 WGR
_____ 1.8 km
- ↶ 2. Turn left at the 1st cross street onto Concession Rd 2 WGR
_____ 1.9 km
- ↶ 3. Turn left onto 21 Rd
_____ 1.6 km
- ↗ 4. 21 Rd turns slightly right and becomes Baseline Rd
_____ 190 m
- ↶ 5. Turn left onto Concession Rd 14
_____ 2.1 km
- ↶ 6. Turn left onto Side Rd 25
_____ 2.2 km
- ↶ 7. Turn left onto Concession Rd 12
_____ 2.0 km



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 1 km


Concession Rd 14

West Grey, ON N0G 2M0

- ↑ 1. Head west on Concession Rd 14 toward Side Rd 25
_____ 1.6 km
- ↶ 2. Turn left onto Side Rd 25
_____ 2.2 km
- ↶ 3. Turn left onto Concession Rd 12
_____ 3.9 km
- ↶ 4. Turn left onto Concession Rd 2 WGR
_____ 1.9 km
- ↶ 5. Turn left onto 21 Rd
_____ 1.6 km
- ↗ 6. 21 Rd turns slightly right and becomes Baseline Rd
_____ 190 m
- ↶ 7. Turn left onto Concession Rd 14
_____ 400 m

Concession Rd 14

West Grey, ON N0G 2M0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 500 m


Concession Rd 14

West Grey, ON N0G 2M0

- ↑ 1. Head west on Concession Rd 14 toward Side Rd 25
_____ 1.9 km
- ↪ 2. Turn right onto Side Rd 25
_____ 2.1 km
- ↪ 3. Turn right onto Concession Rd 16
_____ 2.4 km
- ↪ 4. Turn right onto Baseline Rd
_____ 2.0 km
- ↪ 5. Turn right onto Concession Rd 14
_____ 450 m

Concession Rd 14

West Grey, ON N0G 2M0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 1 km


174598-174400 Mulock Rd

Elmwood, ON N0G 1S0

- ↑ 1. Head north on Mulock Rd toward Concession Rd 12
_____ 1.8 km
- ↶ 2. Turn left at the 1st cross street onto Concession Rd 12
_____ 4.1 km
- ↶ 3. Turn left onto Grey Road 3/County Rd 3
_____ 2.1 km
- ↶ 4. Turn left onto Concession 10 Ndr/Concession Rd 10
_____ 4.4 km
- ↶ 5. Turn left onto Mulock Rd
_____ 210 m

174401-174599 Mulock Rd

Elmwood, ON N0G 1S0



Imagery ©2024 Airbus, CNES / Airbus, Landsat / Copernicus, Maxar Technologies, Map data ©2024 Google 1 km

174401-174599 Mulock Rd
Elmwood, ON N0G 1S0

- ↑ 1. Head north on Mulock Rd toward Concession Rd 12
_____ 1.7 km
- ↘ 2. Turn right at the 1st cross street onto Concession Rd 12
_____ 2.8 km
- ↘ 3. Turn right onto Baseline
_____ 2.0 km
- ↘ 4. Turn right onto Concession 10 Ndr/Concession Rd 10
_____ 2.8 km
- ↘ 5. Turn right onto Mulock Rd
_____ 150 m

174433 Mulock Rd
Elmwood, ON N0G 1S0

APPENDIX F

PUBLIC INFORMATION CENTRE FEEDBACK

Table F1: PIC Feedback

Form of Communication	Summary of Comments
PIC Comment Sheet	<ul style="list-style-type: none"> - Structure G-037 floods between the south bend and Vinegar Hill - Flooding will trap families between the bridge and south bend - Closure would create a significant detour
PIC Comment Sheet	<ul style="list-style-type: none"> - Concerned over the weighting for local access - A bridge that bisects a single property would outweigh a road segment that contains over 10 properties - Budget should be allocated for maintenance as opposed to building new
PIC Comment Sheet	<ul style="list-style-type: none"> - The closure of Structure N-056 creates an inconvenient detour
Online Feedback Form	<ul style="list-style-type: none"> - Proposal for using metal plates on Structure N-055 to restrict access to only allow snowmobiles - The Hampden Bridge is the main connecting trail for Durham
Online Feedback Form	<ul style="list-style-type: none"> - When roads are closed, Concession 2 NDR is a major east-west route - The closure of Kennedy Bridge creates a lengthy detour - Many farmers and residents used this road to travel freely
Online Feedback Form	<ul style="list-style-type: none"> - Gravel pit traffic on Concession 4 NDR will accelerate deterioration of bridges on this road - Cost should be covered by applicants, not the taxpayers
Online Feedback Form	<ul style="list-style-type: none"> - Is there an option for temporary repair options for Structure N-055 and N-056 - Difficult to take farm equipment anywhere with closures
Online Feedback Form	<ul style="list-style-type: none"> - All bridges need to be in working order eventually - Structures need to be maintained

Online Feedback Form	<ul style="list-style-type: none">- Would like to see Kennedy Bridge repaired
Online Feedback Form	<ul style="list-style-type: none">- Bridge near Priceville and Artemesia-Glenelg Townline needs attention as it is too narrow and rough
Email	<ul style="list-style-type: none">- Gravel pits operating at the corner of Concession 4 NDR and Allan Park Road have significantly increased heavy truck traffic in the surrounding area- With Kennedy Bridge closed there are concerns that once Structure B-003 is closed on Concession 6 NDR, Concession 4 NDR will see a large increase in traffic volume and deterioration of those structures